HOUSTON LIGHTING AND POWER W.A. PARISH GENERATING STATION THOMPSONS, FORT BEND COUNTY, TX EPA CERCLA ID NO.: TXD097311849

Prepared for

U.S. Environmental Protection Agency Region 6 1445 Ross Avenue Dallas, TX 75202

Contract No.: 68-W5-0019
Work Assignment No.: 06-97-03-0004
Document Control No.: START-06-F-H0001

Prepared by

Roy F. Weston, Inc. 5599 San Felipe, Suite 700 Houston, TX 77056

September 1997



HOUSTON LIGHTING AND POWER W.A. PARISH GENERATING STATION THOMPSONS, FORT BEND COUNTY, TX EPA CERCLA ID NO.: TXD097311849

September 1997

SIGNATURE PAGE

	Susan Webster Superfund Site Assessments (6SF-RA) U.S. Environmental Protection Agency Work Assignment Manager	Date
	B. E. O.	9/3/47
راً	John D. DiFilippo, P.E.	Date
tuc	Roy F. Weston, Inc.	
	Zone Program Manager	
FOR	Robert B. Beck, P.E. Roy F. Weston, Inc.	9/4/94 Date
	Site Manager	
	Cecilia H. Shappee, P.E. Roy F. Weston, Inc. Quality Assurance Officer	9/4/97 Date
	Carol La Breche, P.E. Roy F. Weston, Inc.	9/4/97 Date
	Project Team Leader	
	TIOJOOL TOMILITOMOL	

HOUSTON LIGHTING AND POWER W.A. PARISH GENERATING STATION THOMPSONS, FORT BEND COUNTY, TX EPA CERCLA ID NO.: TXD097311849

TABLE OF CONTENTS

SEC	CTION	TITLE		PAGE
				
1	INTR	ODUCTION		1-1
	1.1		THE INVESTIGATION	
	1.2	SCOPE OF WO	ORK	1-1
	1.3		ORGANIZATION	
2	SITE	BACKGROUNI	INFORMATION	2-1
	2.1	SITE LOCATI	ON AND DESCRIPTION	2-1
	2.2		Y	
	2.3	SUMMARY O	F PREVIOUS INVESTIGATIONS	2-3
	2.4	SOURCE WAS	STE CHARACTERISTICS AND SITE CONCERNS	2-5
		2.4.1 Waste S	Source Characteristics	2-5
		2.4.1.1	SWMU 1—Demineralizer Acid/Base Regeneration	
			Wastewater Surface Impoundment 1	2-6
		2.4.1.2		
			Wastewater Surface Impoundment 2	2-7
		2.4.1.3	SWMU 3—Demineralizer Acid/Base Regeneration	
			Wastewater Surface Impoundment 3	2-8
		2.4.1.4	SWMU 4—Chemical Waste Treatment System	2-8
		2.4.1.5	SWMU 5—Inorganic Metal Cleaning Wastewater Surface	е
			Impoundment 1	2-9
		2.4.1.6	SWMU 6—Inorganic Metal Cleaning Wastewater Surface	е
			Impoundment 2	
		2.4.1.7	SWMU 7— Inorganic Metal Cleaning Wastewater Surface	e
			Impoundment 3	2-10
		2.4.1.8	SWMU 8—Organic Metal Cleaning Waste Surface	
			Impoundment	2-11
		2.4.1.9	SWMU 9—Inorganic Acid/Ash Collection Surface	
			Impoundments	2-12

HOUSTON LIGHTING AND POWER W.A. PARISH GENERATING STATION THOMPSONS, FORT BEND COUNTY, TX EPA CERCLA ID NO.: TXD097311849

TABLE OF CONTENTS (Continued)

SECTION	TITLE		PAGE
		2.4.1.10 SWMU 10—Industrial Landfill and Overflow Collection	
		Pond	2-12
		2.4.1.11 SWMU 11—Waste Oil and Sludge Collection Facilities	2-13
		2.4.1.12 SWMU 12—90-Day Maximum Hazardous Waste Storage	
		Area	
		2.4.1.13 SWMU 13—Bulk Storage Area	
		2.4.1.14 SWMU 14—Nonhazardous Construction Debris Landfill	
	2.4.2	Summary of Waste Source Characterization	
	2.4.3	Waste Source Conclusions	
	2.4.4	Site Concerns	2-16
3 EX	DOCI IDE	AND MIGRATION PATHWAY CHARACTERISTICS	2 1
3.1		UNDWATER PATHWAY	
J.1	3.1.1	Hydrogeologic Description	
	3.1.1	, , , , , , , , , , , , , , , , , , , ,	
	3.1.2	Groundwater Pathway Targets.	
3.2		FACE WATER PATHWAY	
3.2	3.2.1		
		Likelihood to Release	
	3.2.3	Surface Water Pathway Targets	
3.3		EXPOSURE.	
5.5	3.3.1	Surficial Conditions	
	3.3.2	Likelihood of Exposure	
	3.3.3	Soil Exposure Targets	
3.4		ATHWAY	
J.4	3.4.1	Atmospheric Conditions	
	3.4.2	Likelihood to Release	
	3.4.3		

HOUSTON LIGHTING AND POWER W.A. PARISH GENERATING STATION THOMPSONS, FORT BEND COUNTY, TX EPA CERCLA ID NO.: TXD097311849

TABLE OF CONTENTS (Continued)

SEC	TION	TITLE	PAGE
	3.5	DATA GAPS	3-4
4	SAM	4-1	
	4.1	BACKGROUND INFORMATION	4-1
	4.2	WESTON SAMPLING ACTIVITIES	
	4.3	REPORT PREPARATION	4-1
5	PRO	JECT INFORMATION	5-1
	5.1	PROJECT SCHEDULE	5-1
6	REF	ERENCES	6-1

APPENDIX

A Health And Safety Plan

HOUSTON LIGHTING AND POWER W.A. PARISH GENERATING STATION THOMPSONS, FORT BEND COUNTY, TX EPA CERCLA ID NO.: TXD097311849

LIST OF FIGURES

FIGU	URE TITLE	PAGE
1-1	Site Location Map	
2-1	Site Area Map	
2-2	Site Plan	2-19
	LIST OF TABLES	
TABI	LE TITLE	PAGE
2-1	Summary of Potential Waste Sources	2-20
5-1	Project Schedule (1997)	5-2

SECTION 1 INTRODUCTION

Under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and Reauthorization Act of 1986 (SARA), Roy F. Weston, Inc. (WESTON_☉) has been tasked to perform a Site Inspection (SI) of the Houston Lighting and Power W.A. Parish Generating Station (HL&P) site (EPA CERCLA Identification Number TXD097311849) in Thompsons, Fort Bend County, Texas (Figure 1-1). Based on available site information, WESTON believes that the site is eligible for action under CERCLA/SARA. The U.S. Environmental Protection Agency (EPA) Region 6 retained WESTON to complete this investigation under EPA Contract Number 68-W5-0019 and Work Assignment Number 06-97-03-0004.

This document represents the Task Work Plan (TWP) for the SI. The purpose of this document is to summarize available background information for the site and, based on this information and the results of a site reconnaissance, propose any additional investigation activities required for completion of the SI.

1.1 PURPOSE OF THE INVESTIGATION

The SI is the second investigation in a series of screening assessments in which EPA evaluates hazardous waste sites under CERCLA/SARA. The purpose of this SI is to identify immediate or potential threats that hazardous substances attributable to the site may pose to human health and the environment by documenting the existence and migration of hazardous substances related to the site and by identifying the receptors, or targets, potentially exposed to the hazardous substances. EPA will use the information obtained during the SI to evaluate the site using the Hazard Ranking System (HRS) and to help decide if the site is a potential candidate for inclusion on the National Priorities List (NPL). Depending on the results of the SI, EPA may propose the site for listing on the NPL, decide that further investigation of the site is required, or determine that no further action should be taken at the site under CERCLA/SARA.

1.2 SCOPE OF WORK

The scope of work for the SI will focus on obtaining the most important background information and analytical data required to evaluate the site using the HRS. WESTON will complete the following major tasks as part of this SI:

- Obtain and review available background information concerning the site.
- Research data related to the groundwater, surface water, soil exposure, and air pathways.


- Conduct a site reconnaissance survey to document current site conditions, to locate potential hazardous waste sources, and to identify potential receptors or targets of a release.
- Prepare a site-specific TWP and a Health and Safety Plan (HASP) describing planned investigation activities and appropriate safety protocol.
- Prepare a Site Inspection Report within the HRS framework, which presents the background information obtained for the site and documents the results of the site reconnaissance and analytical data review.

1.3 WORK PLAN ORGANIZATION

This SI TWP has been organized in a format that is intended to facilitate application of information in the report to the HRS. This TWP is organized as follows:

- Section 1—Introduction
- Section 2—Site Background Information
- Section 3—Exposure and Migration Pathway Characteristics
- Section 4—Sampling Visit Activities
- Section 5—Project Information
- Section 6—References

A copy of the limited HASP is provided in Appendix A. All referenced figures and tables are found at the end of each section.



SECTION 2 SITE BACKGROUND INFORMATION

A summary of the location, description, operational history, hazardous waste characteristics, and concerns of the site is presented in the following subsections. The site background information presented in this TWP has been obtained from reports previously completed for the site, as well as from WESTON's recent site reconnaissance.

2.1 SITE LOCATION AND DESCRIPTION

The HL&P site is located at 2759 Jones Road, Thompsons, Fort Bend County, Texas. The site can be reached by traveling south from the City of Houston on U.S. Highway 59 (Hwy. 59). Exit at Crabb River Road and travel approximately 2 miles south on Crabb River Road, continue 3 miles south on FM 762, then travel 3 miles east on Jones Road. The site is located approximately 3 miles southwest of the Town of Thompsons and adjacent to Smithers Lake. The geographic coordinates of the site are approximately 29°28'45" north latitude and 95°38'05" west longitude (Reference 1). A Site Area Map derived from the U.S. Geological Survey (USGS) 7.5-minute topographic quadrangle maps of Smithers Lake, Missouri City, Sugar Land, and Thompsons, Texas, is provided as Figure 2-1 (Reference 2).

WESTON contacted Mr. Robert Moles, HL&P Parish Station General Manager, at PO Box 98 Thompsons, Texas 77481 in May 1997. Mr. Robert Moles signed an EPA Access Agreement on 8 May 1997, allowing WESTON access to the HL&P site to complete the SI (Reference 3). WESTON conducted an on-site reconnaissance of the HL&P site and the surrounding area on 22 May 1997.

The HL&P site consists of a coal and gas power production facility covering approximately 3,000 acres (Reference 4). Access to the property is restricted by a fence and a security gate at the entrance to the plant. During business hours, a security guard occupies the guard house at the entrance to the facility; otherwise, the gate is locked. A Site Plan is provided as Figure 2-2. Notable site features of the power plant include an administration building, a coal pile, a paved parking lot, and fourteen solid waste management units (SWMU), described below (References 4 and 5):

- SWMU 1—An open tank settling basin used for the collection of low-volume chemical wastes.
- SWMU 2—A sump used for temporary storage of demineralizer wastewater prior to transfer into SWMU 1.
- SWMU 3—Another settling basin for low-volume chemical wastes.
- SWMU 4—Two chemical treatment systems for discharge from SWMUs 1 and 3.

- SWMU 5—A holding basin for discharge to SWMU 4.
- SWMU 6—A sump to collect discharge to SWMU 5.
- SWMU 7—A surface impoundment that collects inorganic metal cleaning wastewater. Contents are sent to SWMU 4 for treatment.
- SWMU 8—A surface impoundment containing organic metal cleaning waste. The organic sludge is burned in two boilers.
- SWMU 9—Three former temporary inorganic acid storage ponds.
- SWMU 10—A Class II nonhazardous waste industrial landfill area.
- SWMU 11—Three waste oil collection facilities.
- SWMU 12—An outside drum storage area on a concrete slab.
- SWMU 13—A bulk storage area that is only used intermittently during facility maintenance.
- SWMU 14—A landfill that is used for the on-site disposal of construction demolition debris.

Other site features include Smithers Lake, Dry Creek, and Rabbs Bayou. The site is bounded to the north by Smithers Lake, to the south by Jones Road, and to the west and east by open areas of vegetation (Reference 2). Presently, there are nine monitoring wells and seven potable water wells on site (References 6 and 7).

2.2 SITE HISTORY

The HL&P site is privately owned by Houston Light and Power. The W.A. Parish Generating Station began operating in 1958 with gas-fired turbine units. Two coal-fired units were constructed between 1974 and 1978, and coal operations began in 1978. Two more coal-fired units came on-line in 1980 and 1982 (Reference 4). The plant produces electricity by generating steam from both gas-operated and coal-fired turbines. Process water is routed through chemical treatment systems to remove suspended solids and adjust pH. Treated wastewater is discharged into Smithers Lake. Sludges remaining on the floor of surface impoundments are periodically removed and sent through a rotary vacuum to remove moisture. Dried sludge, bottom ash, and fly ash are stored in cells located within an on-site nonhazardous industrial landfill. Bottom ash and fly ash are sold for recovery. Flue gas desulfurization sludge is dewatered and stored in the industrial landfills. Oil and oil sludge generated on-site are drummed and stored for off-site

disposal. All other waste associated with the power plant operations are stored for off-site disposal.

In 1977, three inorganic acid storage ponds (SWMU 9) were excavated for temporary use during the construction of two units of the chemical waste treatment system. On an intermittent basis, the natural clay-lined impoundments were used for the disposal of a mixture of chemical cleaning waste from the feedwater and boiler (References 4 and 5). In 1978, analytical results and information concerning the sampling of waste from the temporary surface impoundments indicated that the waste contained elevated concentrations of metals (Reference 8). HL&P files indicated at the time of the sampling event, the impoundments held approximately 6,400,000 gallons of wastewater (Reference 8). No wastewater was stored in the three impoundments after early 1980. By March 1982, all three impoundments had been backfilled and graded over following waste removal. Soil was not removed from the impoundment during this activity (Reference 9).

2.3 SUMMARY OF PREVIOUS INVESTIGATIONS

WESTON reviewed available EPA CERCLA files and background information provided by HL&P. Based on this file information, previous investigations performed for the HL&P site include the following:

- In 1976, McClelland Engineers, Inc. conducted a geotechnical investigation at the ash storage area (SWMU 10) (Reference 10). Soil borings indicated relatively uniform soil conditions throughout the tract that consisted primarily of highly plastic clays of CH classification to about a 30-foot depth underlain by silty fine sand to the maximum depth explored, 60 feet. The report also concluded that the 4 feet of natural silty clay-plastic clay (CL-CH) soils in the ash storage area (SWMU 10) would provide a suitable liner for all the cells in the landfill. Thus, additional compacted clay or artificial liners were not needed. However, the report also indicated that localized deposits of silts that may be present at the excavation's finished grade should be excavated and replaced by compacted clay.
- On 8 June 1983, an Open Dump Inventory inspection was conducted by Texas Department of Water Resources (TDWR) (Reference 11). The inspector indicated that runoff from the landfill cells in SWMU 10 was not contained, because the landfill cells were not diked or bermed and were located next to Rabbs Bayou. The SWMU was found to be compliant with all other criteria.
- In 1985, Resource Engineering conducted a hydraulic evaluation to assess the need for groundwater monitoring in the vicinity of SWMU 10, the industrial landfill (Reference 12). Data generated from a cone penetrometer survey were used to develop six stratigraphic cross sections, which characterized the soil profile across the area. The profiles indicated that the potential for groundwater contamination was low. However, Resource Engineering recommended a conservative approach

by installing two monitoring wells within shallow sand zones. The report recommended both wells would screen the entire sand layer and would help to establish the hydraulic gradient and to provide monitoring of the hydrogeologic unit.

- On 28 January 1986, EPA issued a Notice of Violations citing 18 violations of untreated wastewater releases into Smithers Lake during 1985. These violations were attributed to mechanical breakdowns, and corrective actions were addressed in Houston Lighting and Power's Answer to Findings of Violation and Administrative Order of 28 January 1986, dated 3 March 1986 (Reference 13).
- In 1988, A.T. Kearney, Inc. conducted a review of the state's interim status cleanclosure determination of the outdoor container storage area (SWMU 12) for the EPA, Region 6 (Reference 14). The A.T. Kearney, Inc. review found the closure had not met the closure performance standard of 40 CFR 265.111. The Closure Plan and Certification of Closure did not demonstrate how closure activities controlled, minimized, or eliminated post-closure escape of hazardous waste, contaminated runoff, or hazardous waste decomposition products to the ground or surface water or to the atmosphere (Reference 14). On 25 September 1995, the Texas Water Commission (TWC) approved the closure (Reference 15).
- In July 1990, ICF Technology, Inc. conducted a Preliminary Assessment (PA) under contract to EPA, Region 6. CERCLA, TWC, and National Pollutant Discharge Elimination System (NPDES) files were searched for available information. A site reconnaissance was not conducted. The PA indicated that the site contained eight surface impoundments, two chemical waste treatment systems, three acid collection/ash ponds, a lagoon storage area, waste oil and oil sludge collection systems, two less than 90-day container storage areas, one bulk storage area, and a landfill (Reference 4).

The PA reported concern with the contaminants found in a TWC Notice of Solid Waste Management Registration and laboratory data from samples collected by HL&P on 11 March 1983 for Extraction Procedure Toxicity (EP Toxicity) tests. Sample analysis of demineralizer regenerant wastewater, metal cleaning inorganic acids (wastewater and sludge), and metal cleaning organic acids revealed arsenic, barium, cadmium, chromium, endrin, lead, lindane, selenium, and toxaphane in trace amounts. The TWC registration form listed acetone, asbestos, mercury, and polychlorinated biphenyl (PCB) contaminated solids and fluids as having been stored on-site.

The PA report concluded that waste migrations to groundwater, surface water, and air and soil exposure were a concern due to the targets in each pathway. On 2 August 1990, based on the findings of the PA, EPA recommended a site sampling investigation be performed on the HL&P site in order to document the

potential for or extent of any contamination in the groundwater and surface water pathway (References 16 and 17).

Presently, the plant is not permitted under Resource Conservation and Recovery Act (RCRA). However, the plant is an industrial solid waste management facility regulated by the Texas Natural Resource Conservation Commission (TNRCC). All hazardous waste generated at the site is stored in RCRA-compliant units for less than 90 days and shipped off-site (Reference 5). The plant applied for a Part A permit under RCRA in the early 1980s, but this application was later retracted (Reference 18). All outfalls of discharge water into Smithers Lake are regulated by a NPDES permit (Reference 5).

2.4 SOURCE WASTE CHARACTERISTICS AND SITE CONCERNS

Information concerning the known or potential waste sources at the HL&P site and the constituents thought to be associated with each source are described in the following subsections along with potential concerns associated with contaminant migration and exposure.

2.4.1 Waste Source Characteristics

The following subsections summarize each of the fourteen potential waste sources at the HL&P site that were identified in the 1990 PA. In order to describe each potential waste source, each subsection will be subdivided as follows:

- <u>Activity</u>—A description of waste generation and containment features of the SWMU.
- Existing Permit—The permit associated with the SWMU and/or its outfall.
- Monitoring—The type and frequency of monitoring associated with the SWMU and/or its permit and a summary of the monitoring results.
- <u>Concerns</u>—Compliance status and/or comments associated with the SWMU.

Information concerning the following subsections was collected from the following sources:

- The 1990 PA by ICF Technology (Reference 4).
- WESTON's field log book (Reference 5).
- McClelland Engineers' Geotechnical Investigation of Ash Storage Area (Reference 10).

- Wastewater discharge data sample results from February and March 1997 for various NPDES-permitted outfalls that are associated with SWMUs 1, 3, 5, 7, 10, and 11 (Reference 19).
- The 12 April 1985 memorandum outlining the guidelines for the Class III construction debris landfill, SWMU 14 (Reference 20).
- The 2 July 1996 TNRCC Notice of Registration (NOR) (Reference 21).
- NPDES permit information (fax) (Reference 22).
- October 1996 groundwater data from the sampling of the monitoring wells surrounding SWMU 10 (Reference 23).
- Wastewater Permit Exceedence Notification prepared by HL&P, January 1996 to June 1997 (Reference 24).
- Telephone call with Lucien Klejbuck of HL&P (Reference 25).
- November 1995 Application for an Amendment to TNRCC Permit No. 5794 for the Injection of Boiler Cleaning Wastewater into Stream Generating Units 5 and 6 (Reference 26).
- TNRCC Permit No. 6430A, Fly Ash-Bottom Ash Disposal System (Reference 27).
- The 1996 maximum contaminant level (MCL) list of metal concentrations in groundwater (Reference 28).

2.4.1.1 SWMU 1—Demineralizer Acid/Base Regeneration Wastewater Surface Impoundment 1

Activity

The impoundment is an above-grade, fiberglass-lined concrete open tank settling basin having two compartments holding 232,000 gallons each. It is used for the collection of low-volume chemical wastes including make-up demineralizer regenerant; condensate polisher backwash; boiler area, fly ash silo, and area and precipitator washdown wastes. This waste is classified as Class II waste. Waste from the settling basin is sent to the chemical waste treatment system (SWMU 4). Accumulated sludge is periodically removed from the basin floors and is sent to the sludge dewatering system portion of SWMU 4. After treatment, the wastewater is discharged by internal outfall 203 into Smithers Lake. It should be noted that wastewater from the aforementioned internal outfall 203, and internal outfalls 103, 403, 703, 603, 303, and 803 that shall be discussed later in this text combine into outfall 003, which discharges directly into Smithers Lake.

Existing Permit

The internal outfall associated with this SWMU, 203, is permitted under the NPDES program and under TNRCC discharge permit number TX0006394.

Monitoring

Discharge from outfall 203 is monitored daily for flow rate and weekly for total suspended solids (TSS) and oil and grease. Outfall 003 is monitored continuously for temperature and flow rate, and weekly for total residual chlorine, and biomonitored once every six months. The results are self-reported to TNRCC.

Concerns

The current compliance status of outfalls 203 and 003 is unknown. However, the exceedence summary for January 1996 to June 1997 submitted to TNRCC reported no exceedences for these outfalls.

2.4.1.2 SWMU 2—Demineralizer Acid/Base Regeneration Wastewater Surface Impoundment 2

Activity

The impoundment is a below-grade, fiberglass-lined concrete sump tied to SWMU 1 and has a storage capacity of 82,000 gallons. It is used for the temporary storage of demineralizer wastewater prior to transfer to a chemical waste treatment system. The accumulated demineralizer regenerant inorganic sludge is periodically removed from the sump floor and is sent to the sludge dewatering system. After treatment the wastewater is discharged into Smithers Lake by internal outfall 203.

Existing Permit

Because SWMU 2 is tied to SWMU 1, the internal outfall associated with this SWMU is outfall 203. This outfall is permitted under the NPDES program and under TNRCC discharge permit number TX0006394.

Monitoring

Discharge from outfall 203 is monitored daily for flow rate and weekly for total suspended solids (TSS) and oil and grease. Outfall 003 is monitored continuously for temperature and flow rate, and weekly for total residual chlorine, and biomonitored once every six months. The results are self-reported to TNRCC.

Concerns

The current compliance status of outfall 203 is unknown. However, the exceedence summary for January 1996 to June 1997 submitted to TNRCC reported no exceedences for this outfall.

2.4.1.3 SWMU 3—Demineralizer Acid/Base Regeneration Wastewater Surface Impoundment 3

Activity

The impoundment is an above-grade, fiberglass-lined concrete open settling basin tied to SWMU 1 and has a storage capacity of 82,000 gallons. It is used for the collection of low-volume chemical wastes prior to transfer through outfall 403 to a chemical waste treatment system. The accumulated demineralizer regenerant inorganic sludge is periodically removed from the basin floors and is sent to the sludge dewatering system. After treatment, the wastewater is discharged into Smithers Lake by outfall 703.

Existing Permit

Outfalls 403 and 703 are permitted under the NPDES program and under TNRCC discharge permit number TX0006394.

Monitoring

Discharge from outfall 403 and 703 is monitored daily for flow rate and weekly for TSS and oil and grease.

Concerns

The current compliance status of outfall 703 is unknown. However, the exceedence summary for January 1996 to June 1997 submitted to TNRCC reported that in December 1996 the daily maximum oil and grease in outfall 703 exceeded the permitted daily maximum. Twenty-four hour notification of this event was provided to TNRCC. The exceedence was believed to be the result of sulfur in the waste stream from the flue gas desulfurization system (FGDS). Procedures that control the volume of wastewater from the FGDS are reportedly being reviewed (Reference 24).

2.4.1.4 SWMU 4—Chemical Waste Treatment System

Activity

The chemical waste treatment system is a treatment system for discharge from SWMUs 1 and 3. The system consists of two steel-constructed clarifiers with a capacity of approximately 902,000 gallons and 1,842,000 gallons. A 6-inch-curbed concrete dike surrounds the clarifiers.

This concrete dike is designed to direct any spills or runoff into a collection sump. The collected water from the sump is sent back to the wastewater treatment system.

The clarifiers consist of solids contact clarifiers and primary and secondary pH adjustment control system reaction mixing tanks for suspended solids removal and pH adjustment. The sludge generated in the chemical waste treatment systems, containing demineralizer regenerant, boiler blowdown and inorganic metal cleaning waste, is pumped to the sludge dewatering system, which is separate from SWMU 4. The sludge is removed to a thickener and sent through a rotary vacuum filter. Dried sludge is trucked to the industrial landfill (SWMU 10). The wastewater from SWMU 4 is eventually discharged into Smithers Lake by internal outfalls 103, 203, 603, and 703.

Existing Permit

These outfalls are permitted under the NPDES program and under TNRCC discharge permit number TX0006394.

Monitoring

The type and frequency of monitoring for outfalls 103, 203, 603, and 703 are covered in Subsections 2.4.1.1, 2.4.1.3, 2.4.1.5, and 2.4.1.7.

Concerns

Concerns and comments associated with the outfalls of this SWMU are discussed in Subsections 2.4.1.1, 2.4.1.3, 2.4.1.5, and 2.4.1.7.

2.4.1.5 SWMU 5—Inorganic Metal Cleaning Wastewater Surface Impoundment 1

Activity

The impoundment is an above-grade, fiberglass-lined concrete basin with two compartments holding 850,000 gallons each. It is used for the collection of inorganic metal cleaning wastes. These wastes include hydrochloric acid boiler cleaning wastes, boiler blowdown, and air preheater wash. The wastes are collected for treatment in Units 5 and 6 of SWMU 4 for pH adjustment, metal precipitation, and sedimentation. The metal cleaning inorganic sludge from the basin floors are periodically sent to the sludge dewatering system. The waste is classified as Class II waste. The treated wastewater is discharged through outfall 103 into Smithers Lake.

Existing Permit

Outfall 103 is permitted under the NPDES program and under TNRCC discharge permit number TX0006394.

Monitoring

Discharge from outfall 103 is monitored daily for flow rate and weekly for TSS, oil and grease, iron, and copper.

Concerns

The current compliance status of outfall 103 is unknown. However, the exceedence summary for January 1996 to June 1997 submitted to TNRCC reported no exceedences for this outfall.

2.4.1.6 SWMU 6—Inorganic Metal Cleaning Wastewater Surface Impoundment 2

Activity

The impoundment is actually a sump for discharge to SWMU 5 that consists of two below-grade, fiberglass-lined concrete basins holding 21,000 gallons and 54,000 gallons. The waste is classified as Class II waste. The treated wastewater is discharged through outfall 103 into Smithers Lake.

Existing Permit

Outfall 103 is permitted under the NPDES program and under TNRCC discharge permit number TX0006394.

Monitoring

Discharge from outfall 103 is monitored daily for flow rate and weekly for TSS, oil and grease, iron, and copper.

Concerns

The current compliance status of outfall 103 is unknown. However, the exceedence summary for January 1996 to June 1997 submitted to TNRCC reported no exceedences this outfall.

2.4.1.7 SWMU 7—Inorganic Metal Cleaning Wastewater Surface Impoundment 3

Activity

The impoundment is an above-grade, fiberglass-lined concrete basin with two compartments holding 1,189,000 gallons each. The basin collects inorganic metal cleaning wastes, including hydrochloric acid boiler cleaning wastes, boiler blowdown, and air preheater wash prior to treatment in SWMU 4. The sludge from the basin floor is periodically sent to the sludge dewatering system. The waste is classified as Class II waste. The treated wastewater is discharged through internal outfall 603 into Smithers Lake.

Existing Permit

Outfall 603 is permitted under the NPDES program and under TNRCC discharge permit number TX0006394.

Monitoring

The outfall is monitored daily for flow rate and weekly for TSS, oil and grease, iron, and copper.

Concerns

The current compliance status of outfall 603 is unknown. However, the exceedence summary for January 1996 to June 1997 submitted to TNRCC reported no exceedences for this outfall.

2.4.1.8 SWMU 8—Organic Metal Cleaning Waste Surface Impoundment

Activity

The impoundment is a below-grade, fiberglass-lined concrete basin with two compartments holding 173,922 gallons each. The organic metal cleaning wastes consist of hydroxyacetic-formic acid and ammoniated citric acid used in cleaning boilers and equipment. The waste is burned in two boilers. The boiler ash is stored in the industrial landfill (SWMU 10).

Existing Permit

The air emissions of the two boilers are permitted under TNRCC permit number 5794.

Monitoring

Air emissions monitoring is conducted by collecting a wastewater sample from each concrete basin prior to injection into the boilers. The wastewater is sampled for metallic oxides and salts, chlorides, fluorides, and nitrates. Additional monitoring of these units is related to the 1990 Clean Air Act and the Acid Rain Provisions as specified under 40 CFR 75. This consists of continuous stack monitoring of nitrogen oxides (NO_x), sulfur dioxide (SO₂), and carbon dioxide (CO₂) along with stack flow and opacity.

Concerns

Information concerning the compliance status of the boilers was not available. However, the existing air permit indicated that the stacks of the boilers are continuously monitored. In addition, to insure compliance with the permit requirements, a wastewater sample is collected from each concrete basin and analyzed prior to injection into the boilers. When verification of the chemical constituent ranges in the permit is confirmed, then permission to inject the wastewater into the boiler is given.

2.4.1.9 SWMU 9—Inorganic Acid/Ash Collection Surface Impoundments

Activity

In 1977, three inorganic collection surface impoundments comprised of 0.56 acres (500,000 gallons), 0.75 acres (1,000,000 gallons), and 4.27 acres (5,000,000 gallons) were excavated for temporary use during the construction of two units of the chemical waste treatment system. On an intermittent basis, the natural clay-lined impoundments were used for the disposal of a mixture of chemical cleaning waste from the feedwater and boiler. In 1978, analytical results and information based on waste sampling of the temporary surface impoundments indicated that the waste reportedly contained concentrations of metals: chromium, copper, manganese, zinc, iron, and sodium. No wastewater entered the three impoundments after early 1980. By March 1982, waste was removed from all three impoundments, backfilled, and graded over. Soil was not removed from the impoundment during this activity.

Existing Permit

No permits are associated with this SWMU.

Monitoring

No monitoring is associated with this SWMU.

Concerns

According to McClelland Engineers 1978 geotechnical report, the geology in the SWMU 10 area provides a natural clay liner that exhibits a coefficient of permeability of 1.0 x 10⁻⁷ centimeters per second (cm/sec) or lower. Contaminants that could migrate to groundwater may be contained by the natural clay soils, however, no studies have been done in the area of SWMU 9. In 1982, the ponds were reportedly backfilled and graded over, thus preventing runoff from the SWMU. The low volatility of the contaminants of concern (metals) greatly diminish the risk of air exposure.

2.4.1.10 SWMU 10—Industrial Landfill and Overflow Collection Pond

Activity

The industrial landfill consists of four cells for the storage of fly, bottom ash, and Class II industrial waste. In Cell 2, fly ash and bottom ash are blended before being spread in the cell to produce a more stable product. Cell 3 at the time of WESTON's site reconnaissance was a new and unused cell designated for bottom ash, and Cell 1A contained Class II industrial waste. Cell 1 contained Class II nonhazardous waste and was closed in 1989. Each landfill cell has a collection pond, which collects the runoff from that cell. All runoff from the landfill cells is pumped to an overflow settling basin pond. The water from the overflow pond is discharged through outfall 004 into Smithers Lake.

Existing Permit

Air emissions from the fly ash and bottom ash disposal system are permitted under the TNRCC Permit No. 5430A. Discharge through outfall 004 is permitted under the NPDES program and under TNRCC discharge permit number TX0006394.

Monitoring

Air emissions of the fly ash and bottom ash blending facility and Cells 2, 3, and 1A are monitored for particulate matter. The discharge through outfall 004 is monitored daily for flow rate, TSS, and oil and grease and bi-monthly for selenium. Chronic biomonitoring tests are conducted quarterly. Although not required by any permit, nine monitoring wells are located around the landfill cells and the overflow pond. These wells are sampled biannually. Samples are analyzed for alkalinity, pH, specific conductance, temperature, turbidity, total dissolved solids, metals, chloride, phosphorus, and sulfate.

Concerns

Based on the PA report and observations made during WESTON's site reconnaissance, all of the SWMUs' cells have synthetic liners. The four existing cells in the landfill area also have a 3-foot natural clay liner. Based on McClelland Engineer's geotechnical investigation, this clay liner has a coefficient of permeability of 1.0 x 10⁻⁷ cm/sec or lower. The overflow pond has a 40 mil (0.040 inches) synthetic liner overlying the natural 3-foot clay liner.

WESTON reviewed the analytical data from the most recent groundwater monitoring sampling event. In October 1996, nine groundwater samples were collected from the nine groundwater monitoring wells located around the industrial landfill area. Groundwater monitoring data generated from the sampling event reported low levels of metals, well below the MCLs in drinking water.

The current compliance status of outfall 004 is unknown. However, the exceedence summary for January 1996 to June 1997 submitted to TNRCC reported no exceedences for this outfall.

2.4.1.11 SWMU 11—Waste Oil and Sludge Collection Facilities

Activity

Three separate waste oil and sludge collection facilities have been documented in previous reports. All three locations are shown on Figure 2-2 (Site Plan Map); however, only two locations were observed during the site reconnaissance. In general, the floor drains in the two observed facilities are located in work locations where potential oil spillage could occur and in equipment operation areas. The floor drains also serve as a containment mechanism for containing rainwater runoff. All of the floor drain treatment system liquid is routed through the facilities oil/water separator and/or concrete lined settling basin. The oil is skimmed from the

wastewater and drummed and stored in a less-than-90-day storage area (SWMU 12) for off-site disposal. The wastewater is routed through outfalls 005, 303, and 803 into Smithers Lake.

Existing Permit

The outfalls are permitted under the NPDES program and under TNRCC discharge permit number TX0006394.

Monitoring

Discharge from outfalls 005, 303, and 803 is monitored daily for flow rate and weekly for TSS and oil and grease. The pH of discharge from outfall 005 is monitored weekly.

Concerns

The current compliance status of outfalls 005, 303, and 803 is unknown. However, the exceedence summary for January 1996 to June 1997 submitted to TNRCC reported one exceedence of TSS from outfall 005, two exceedences of oil and grease from outfall 303, and one exceedence of oil and grease from outfall 803. Most of these exceedences were caused by equipment failures or excessive rainfall. Repairs were completed and procedures were updated. No other exceedences for these outfalls were reported.

2.4.1.12 SWMU 12—90-Day Maximum Hazardous Waste Storage Area

Activity

This area is an outside 90-day maximum hazardous waste storage area consisting of a concrete slab for storage of drums and tanks. Wastes are stored in tanks or drums prior to being shipped off-site to approved hazardous waste treatment facilities. Drums are stored on wooden pallets. Aboveground tanks are contained within 1-foot concrete dikes. One of the waste oil collection facilities (SWMU 11) is contained within the storage area.

Existing Permit

No permits are associated with this SWMU.

Monitoring

No monitoring is associated with this SWMU.

Concerns

There are no concerns associated with the SWMU.

2.4.1.13 SWMU 13—Bulk Storage Area

<u>Activity</u>

The 1990 PA identified a bulk storage area that used bins for the storage of lead-contaminated blasting material prior to off-site disposal. However, during WESTON's site reconnaissance, Houston Lighting and Power indicated that a designated bulk storage area does not exist, but a general area where the bins are used is identified on the Site Plan Map (Figure 2-2). The bins were used during intermittent maintenance.

Existing Permit

No permits are associated with this SWMU.

Monitoring

No monitoring is associated with this SWMU.

Concerns

There are no concerns associated with the SWMU.

2.4.1.14 SWMU 14—Nonhazardous Construction Debris Landfill

Activity

This unit contains only construction demolition nonhazardous waste.

Existing Permit

No permits are associated with this SWMU.

Monitoring

No monitoring is associated with this SWMU.

Concerns

There are no concerns associated with the SWMU.

2.4.2 <u>Summary of Waste Source Characterization</u>

Table 2-1 at the end of this section summarizes the characterization of each waste source.

2.4.3 Waste Source Conclusions

Based on available background information and WESTON's site reconnaissance, the sources at the site consist of seven surface impoundments (SWMUs 1 through 3 and 5 through 8), a chemical waste treatment system (SWMU 4), the closed acid collection/ash surface impoundment (SWMU 9), an industrial landfill area with an overflow pond (SWMU 10), a waste oil and sludge collection facility, and a less-than-90-day hazardous waste storage area (SWMU 12). According to available information, the constituents of concern are mainly metals. However, migration of contaminants of concern are inhibited by liners in the surface impoundments, landfill cells, and overflow pond and a concrete pad in the storage area. These areas are monitored for discharge exceedences by TNRCC under NPDES and air permits and are controlled by run-on and stormwater collection systems. The facility also has it's own Spill Prevention Control and Countermeasures (SPCC) and Pollution Prevention (PPP) Plans. In addition, the three temporary acid collection/ash surface impoundment ponds were backfilled and closed in 1982.


The bulk storage area (SWMU 13) and nonhazardous landfill (SWMU 14) do not pose any potential hazard to human health or the environment, because the storage area is used intermittently during maintenance and the waste stored in the landfill is nonhazardous.

2.4.4 Site Concerns

Possible concerns associated with potential waste sources at the site are the migration of or exposure to hazardous substances attributable to the site through the groundwater, surface water, soil exposure, and air pathways.

- A release to groundwater is of minor concern. The open surface impoundments have fiberglass liners within concrete. The landfill cells have a natural clay liner that has a coefficient of permeability of 1.0 x 10⁻⁷ cm/sec or lower. The closed surface impoundments may have a natural clay liner, however, studies of this area have not been conducted. The 90-day hazardous waste storage area consists of a concrete slab. The tanks stored in this area have secondary containment. Analytical data from the October 1996 monitoring wells sampling event indicated the existence of low levels of metals in the groundwater at the site. However, these levels were below the MCLs for drinking water.
- A release to surface water is of minor concern. All outfalls from the facilities are regulated by TNRCC and are under a NPDES permit. The outfalls are monitored for flow rate, suspended solids, pH, and certain metals of concern. Exceedences and discharges are reported routinely. However, exceedences that have occurred were of short duration due mainly to mechanical failures and excessive rainfall. Necessary repairs were made and procedures were reviewed and revised to mitigate the potential for releases. In addition, the oil drainage collection system also serves as a mechanism for containing rainwater runoff for the facility.

- Soil exposure is of low concern. Much of the facility is covered by buildings and concrete, the entire site is enclosed by a fence, and the plant entrance is monitored by a guard. There are approximately 400 on-site workers.
- A release to air is of low concern. The constituents of concern are metals and have a low volatility. In addition, the boiler stacks and the fly ash and bottom ash hopper are regulated by TNRCC under a current air permit.






TABLE 2-1

SUMMARY OF POTENTIAL WASTE SOURCES

SWMU	DESCRIPTION	PERMIT	MONITORING TYPE/FREQUENCY	CONTAINMENT FEATURES	BASIS OF CONCERN
1	Surface Impoundment	NPDES	Outfalls are monitored daily for flow rate and weekly for TSS.	Fiberglass liner within concrete basin.	Low on all concern associated with this source.
2	Surface Impoundment	NPDES	Outfalls are monitored daily for flow rate and weekly for TSS.	Fiberglass liner within concrete basin.	No concern associated with this source.
3	Surface Impoundment	NPDES	Outfalls are monitored daily for flow rate and weekly for TSS and oil and grease.	Fiberglass liner within concrete basin.	Between January 1996 and June 1997, one exceedence of oil and grease was reported. Procedures for this system are being reviewed. No other exceedences were reported.
4	Steel Clarifiers and Sludge Dewatering	NPDES	Outfalls are monitored daily for flow rate and weekly for one or more of TSS, and oil and grease	6-inch concrete curbed dike designed to direct spills or runoff into a collection sump. The collected water from the sump is sent back to the wastewater treatment system.	No concern associated with this source.
5	Surface Impoundment	NPDES	Outfalls are monitored daily for flow rate and weekly for TSS, oil and grease, iron, and copper.	Fiberglass liner within concrete basin.	No concern associated with this source.

TABLE 2-1 (Continued)

SUMMARY OF POTENTIAL WASTE SOURCES

SWMU	DESCRIPTION	PERMIT	MONITORING TYPE/FREQUENCY	CONTAINMENT FEATURES	BASIS OF CONCERN
6	Surface Impoundment	NPDES	Outfalls are monitored daily for flow rate and weekly for TSS.	Fiberglass liner within concrete basin.	No concern associated with this source.
7	Surface Impoundment	NPDES	Outfalls are monitored daily for flow rate and weekly for TSS, oil and grease, iron, and copper.	Fiberglass liner within concrete basin.	No concern associated with this source.
8	Surface Impoundment	TNRCC Air Permit	Wastewater is sampled for metallic oxides and salts, chlorides, fluorides, and nitrates prior to injection into boilers for confirmation of permitted limits. Stacks of the boilers are continuously monitored for NO _x , SO ₂ , CO ₂ , flow rate, and opacity.	Fiberglass liner within concrete basin.	No concern associated with this source.
9	Three Surface Impoundments	Not Applicable [Closed]	Not Applicable	Natural clay liner. Ponds existed from 1977 to 1982. Wastewater was emptied from the ponds, and the ponds were backfilled and graded over.	No concern associated with this source.

TABLE 2-1 (Continued)

SUMMARY OF POTENTIAL WASTE SOURCES

SWMU	DESCRIPTION	PERMIT	MONITORING TYPE/FREQUENCY	CONTAINMENT FEATURES	BASIS OF CONCERN
10	Industrial Landfill and Overflow Pond	TNRCC Air Permit NPDES	Air emissions of the fly ash and bottom ash blending facility are monitored for particulate matter.	The landfill cells have a 3-foot natural clay liner that has a coefficient of permeability of 1.0 x 10 ⁻⁷ cm/sec or lower.	Based on available information, a release to groundwater from this SWMU has not been documented.
			Wastewater from the overflow pond is monitored daily for flow rate, TSS, and oil and grease and bi-monthly for selenium. Chronic biomonitoring tests are conducted quarterly.	The overflow pond has a 40 mil synthetic liner with a natural 3-foot clay liner underneath.	
			Monitoring wells around the landfills and overflow pond are sampled biannually.		
11	Waste Oil and Sludge Collection Facilities	NPDES	The three outfalls associated with the SWMU are monitored daily for flow rate and weekly for TSS and oil and grease.	The settling basins are concrete lined.	From January 1996 to June 1997, four exceedences of TSS and oil and grease were reported.

TABLE 2-1 (Continued)

SUMMARY OF POTENTIAL WASTE SOURCES

SWMU	DESCRIPTION	PERMIT	MONITORING TYPE/FREQUENCY	CONTAINMENT FEATURES	BASIS OF CONCERN
11 (continued)	Waste Oil and Sludge Collection Facilities	NPDES	The outfall that discharges directly into Smithers Lake (005) is monitored weekly for pH levels.	The waste oil and oil sludge collected from the basins are drummed and stored at SWMU 12 for off-site disposal.	These exceedences were mainly due to mechanical failures and excessive rainfall.
				The oil drainage collection system also serves as a mechanism for containing rainwater runoff for the facility.	Repairs were made and procedures have been revised, and no other exceedences were reported thereafter.
12	Waste Storage Area	Not Applicable	Not Applicable	The area is a 90-day maximum hazardous waste outside storage area consisting of a concrete slab.	No concern associated with this source.
				Drums are placed on wooden pallets.	·
				Aboveground tanks are contained with 1-foot concrete dikes.	

TABLE 2-1 (Continued)

SUMMARY OF POTENTIAL WASTE SOURCES

SWMU	DESCRIPTION	PERMIT	MONITORING TYPE/FREQUENCY	CONTAINMENT FEATURES	BASIS OF CONCERN
13	Bulk Storage Area	Not Applicable	Not Applicable	Not Applicable	No concern associated with this
14	Nonhazardous	Not Applicable	Not Applicable	Not Applicable	No concern associated with this
	Landfill	·	Trot rippilouoio	Two rippitous	source.

SECTION 3 EXPOSURE AND MIGRATION PATHWAY CHARACTERISTICS

Information regarding the groundwater, surface water, soil exposure, and air pathways are presented in the following sections. Sampling and nonsampling data collected to date are addressed. Known data gaps are identified at the end of the section.

3.1 GROUNDWATER PATHWAY

Information concerning the groundwater pathway, generally one of the primary routes of potential hazardous substance migration and exposure, is summarized in the following subsections.

3.1.1 Hydrogeologic Description

The HL&P site is located in the western Gulf Coastal Plain geologic region on the Beaumont Formation and the alluvium of the Brazos River. The Beaumont Formation is principally a poorly bedded, calcareous clay containing thin discontinuous stringers and lenses of silt, sand, and fine sand (Reference 10).

The Beaumont Formation is part of a hydro-stratigraphic unit known as the Chicot aquifer. The thickness of the aquifer increases toward the Gulf of Mexico from zero at the western edge of the Quaternary outcrop (80 miles from the gulf) to more than 1,200 feet at the gulf. The Evangeline aquifer immediately underlies the Chicot aquifer. The Evangeline aquifer thickness is greater, up to 2,000 feet, near the gulf. Both major aquifers indicate regional water flow toward the gulf.

Potentiometric surface maps produced by ERM Southwest, Inc. indicate that groundwater in the vicinity of the site flows in a northeastward direction (Reference 29). Localized flow directions are controlled by surface water bodies including Smithers Lake and the Brazos River. Measurement to depth of groundwater in the boreholes drilled during McClelland Engineers' 1978 geotechnical investigation of the industrial landfill area indicated that the depth to water is 8 to 10 feet below ground surface (bgs) (Reference 10).

3.1.2 Likelihood to Release

Based on available information, a release to groundwater has not been documented at the site. In October 1996, nine groundwater samples were collected from the nine groundwater monitoring wells located around the industrial landfill area (Reference 23). Groundwater monitoring data generated from the sampling event reported low levels of metals. However, these levels were well below the MCLs in drinking water.

Based on the PA report and observations made during WESTON's site reconnaissance, most of the SWMUs have some type of liner (References 4 and 5). The liners of the surface impoundments, chemical waste treatment systems, and container storage area are made of

concrete. The four existing cells in the landfill area have a 3-foot natural clay liner. Based on McClelland Engineers' geotechnical investigation, this clay liner has a coefficient of permeability of 1.0×10^{-7} cm/sec or lower (Reference 10). The overflow pond has a 40 mil synthetic liner overlying a 3-foot natural clay liner. SWMU 9, the former temporary storage ponds, may be lined by a 3-foot natural clay liner.

3.1.3 Groundwater Pathway Targets

According to Houston Lighting and Power, there are nine monitoring wells and seven potable water wells on-site (References 5 and 6). Groundwater is a major source of water supply, providing water for residential use, irrigation of crops, livestock watering, and industrial use (References 12, 30, and 31). Seven irrigation, 28 private drinking water, 10 stock, and 14 public supply wells have been identified within a 4-mile radius of the site (Reference 32).

3.2 SURFACE WATER PATHWAY

Available information concerning the surface water pathway is summarized in the following subsections.

3.2.1 Hydrogeologic Description

According to the PA and observations made during the site reconnaissance, treated wastewater from the power generating facility is discharged into Smithers Lake (References 4 and 5). All run-on to the industrial landfill cells is pumped into an overflow pond, settles in the basin, and then is discharged into Smithers Lake. All outfalls to Smithers Lake from the site are regulated under a NPDES permit.

The PA described the local topography as relatively flat with Smithers Lake at the highest elevation. Natural drainage flows from Smithers Lake to lower elevations through Dry Creek, Rabbs Bayou, and unnamed tributaries to the Brazos River (Reference 4). Flood maps indicate a continued interaction between Smithers Lake and the northern section of Rabbs Bayou (Reference 33).

3.2.2 Likelihood to Release

Based on available information, a release to surface water has not occurred. The drainage system in the industrial landfill area was designed to collect all run-on from the landfill cells into collection ponds. The water is then pumped from the collection ponds into an overflow settling pond. The wastewater is then pumped into Smithers Lake under a NPDES permit. All outfalls into Smithers Lake are regulated by TNRCC under a NPDES permit and are monitored for discharge exceedences. From January 1996 to June 1997, five NPDES permit exceedences of the associated outfalls were reported that were mainly caused by mechanical failures. These failures were corrected, and procedures associated with the operations of the SWMUs are either being reviewed or updated. In addition, the waste oil/oil sludge collection facilities are designed to

collect all stormwater from the power plant facility area. The water is discharged NPDES outfalls to Smithers Lake.

3.2.3 Surface Water Pathway Targets

Surface water pathway targets include drinking water intakes, fisheries, sensitive environments, and other resources that rely on surface water. There are no drinking water intakes. Livestock are occasionally watered from Rabbs Bayou (Reference 4). The PA reported that Worthington Lake, approximately 5 miles downstream, was a bald eagle rookery. Other threatened and endangered species inhabiting Fort Bend County are the Houston toad, American peregrine falcon, arctic peregrine falcon, whooping crane, Eskimo curlew, brown pelican, white-faced ibis, Attwater's greater prairie-chicken, black bear, timber/canebrake rattlesnake, Texas tortoise, and Texas horned lizard (Reference 34).

3.3 SOIL EXPOSURE

Information concerning the soil exposure threat is provided in the following subsections.

3.3.1 Surficial Conditions

Based on observations made during the site reconnaissance, the power plant facility portion of the site is mostly covered by buildings, the plant, a parking lot, and concrete (Reference 5 and Appendix A). Soils at the location of the industrial landfills are classified as the Bernard-Edna series. The Bernard-Edna series is a somewhat poorly drained, very slowly permeable, upland soil. It has a slightly acid, very dark gray clay loam surface, and a very dark gray clay subsoil that is slightly acid in the upper part and neutral to moderately alkaline in the lower part. Slopes range from 0 to 5%, but are mainly less than 1% (Reference 35).

3.3.2 Likelihood of Exposure

Based on observations made during the site reconnaissance and available background information, the site is active, but access to the site is restricted by a perimeter fence. A guard is on duty during the day at the entrance to the plant, otherwise, the entrance is locked. The power plant facility is covered by buildings, concrete, and a parking lot. Three temporary ponds were backfilled and graded over in 1982. Cell 1 in the industrial landfill was closed in 1989.

3.3.3 Soil Exposure Targets

The HL&P site currently consists of an active coal and gas-fired steam-driven electrical generating plant. Approximately 400 workers are present on-site. No residences or schools are located adjacent to the site.

No terrestrial sensitive environments have been identified at the site, and no resources have been identified within the soil exposure pathway.

3.4 AIR PATHWAY

Information concerning the air pathway is presented in the following subsections.

3.4.1 Atmospheric Conditions

Information concerning the weather conditions and patterns in the site vicinity have not been identified.

3.4.2 Likelihood to Release

Based on available information, a release to air has not been documented. A significant release to air is not probable, because the potential contaminants of concern have a low volatility. In addition, the air emissions from the boilers associated with SWMU 8 and the hoppers associated with SWMU 10 are regulated by TNRCC under two air permits.

3.4.3 Air Pathway Targets

Potential targets of the air pathway include on-site workers, the nearby population working and living within 4 miles of the site, as well as any sensitive environments that may be in the area. There approximately 400 workers on-site (Reference 5). According to the PA, land use around the site is primarily livestock ranching and isolated rice growing (Reference 6). Approximately 2 miles away from the site is a bald eagle rookery. The Houston toad, American peregrine falcon, arctic peregrine falcon, whooping crane, Eskimo curlew, brown pelican, white-faced ibis, Attwater's greater prairie-chicken, black bear, timber/canebrake rattlesnake, Texas tortoise, and Texas horned lizard inhabit Fort Bend County (Reference 34).

3.5 DATA GAPS

Based on review of the available background information and observations made during the off-site reconnaissance, the data gaps identified for the site include identification of sensitive environments and an evaluation of atmospheric and climatic conditions at the site.

SECTION 4 SAMPLING VISIT ACTIVITIES

4.1 BACKGROUND INFORMATION

As previously discussed in Section 2, based on available background information and WESTON's site reconnaissance, the sources at the site consist of seven surface impoundments (SWMUs 1 through 3 and 5 through 8), a chemical waste treatment system (SWMU 4), the closed acid collection/ash surface impoundment (SWMU 9), an industrial landfill area with an overflow pond (SWMU 10), a waste oil and sludge collection facility, and a less-than-90-day hazardous waste storage

(SWMU 12). According to available information, the constituents of concern are mainly metals. However, migration of contaminants of concern are inhibited by liners in the surface impoundments, landfill cells, and overflow pond and a concrete pad in the storage area. These areas are monitored for discharge exceedences by TNRCC under NPDES and air permits and are controlled by run-on and stormwater collection systems. The facility also has it's own Spill Prevention Control and Countermeasures (SPCC) and Pollution Prevention (PPP) Plans. In addition, the three temporary acid collection/ash surface impoundment ponds were backfilled and closed in 1982.

The bulk storage area (SWMU 13) and nonhazardous landfill (SWMU 14) do not pose any potential hazard to human health or the environment, because the storage area is used intermittently during maintenance and the waste stored in the landfill is nonhazardous.

4.2 <u>WESTON SAMPLING ACTIVITIES</u>

No field sampling activities will be performed by WESTON during this SI. Under authorization and direction from EPA, WESTON will use all available historical data to complete the SI report.

4.3 REPORT PREPARATION

After reviewing and summarizing the available historical data, WESTON will prepare the final report for the SI. The report format will include the following:

- An introduction section describing the background and purpose of the investigation.
- A site characteristics section describing the site location, operating history, source waste characteristics, and site concerns.
- Individual sections for the groundwater, surface water, soil exposure, and air pathways describing the environmental conditions at the site, the likelihood of a release, targets, and relevant analytical data.

•	A summary and conclusions section discussing the major site concerns.	

SECTION 5 PROJECT INFORMATION

This section outlines basic project management information for the SI. Details concerning key personnel and the project schedule are provided. Reference should be made to WESTON's Generic Site Inspection Work Plan for more detailed information concerning WESTON's project management plan.

5.1 PROJECT SCHEDULE

The overall project schedule is summarized in Table 5-1.

TABLE 5-1 PROJECT SCHEDULE (1997)

TARGET MILESTONES	MAY	JUN	JUL	AUG	SEP
SITE RECONNAISSANCE					
WORK PLAN SUBMITTAL TO EPA					
WORK PLAN REVIEW/APPROVAL BY EPA					
REPORT WRITING					
REPORT QUALITY ASSURANCE					
REPORT SUBMISSION					

SECTION 6 REFERENCES

- 1. WESTON (Roy F. Weston, Inc.). 1997. Standard Operating Procedure to Determine Site Latitude and Longitude Calculation Worksheet for the Houston Lighting & Power W.A. Parish Generating Station Site.
- 2. USGS (U.S. Geological Survey). 1970; 1980 Photorevised. Missouri City, Texas. 1953; 1980 Photorevised. Smithers Lake, Texas. 1953. Thompsons, Texas. 1970; 1980 Photorevised. Sugar Land, Texas (7.5-Minute Series Topographic Quadrangles).
- 3. Moles, Robert. 1997. General Manager, Houston Lighting & Power. Signed Access Request for Houston Lighting & Power W.A. Parish Generating Station to Don Markham, U.S. Environmental Protection Agency (EPA) Region 6, 12 May 1997.
- 4. ICF Technology, Inc. 1990. Preliminary Assessment Report for Houston Lighting & Power W.A. Parish Generating Station. 20 July 1990.
- 5. Tate, Eric. 1997. Roy F. Weston, Inc. Field Logbook Notes for Houston Lighting & Power W.A. Parish Generating Station Site, Fort Bend County, Texas. May 1997.
- 6. Houston Lighting & Power Co. 1996. Groundwater Monitoring Program Sampling and Analysis Quality Assurance Plan. October 1996.
- 7. Bye, R.T. 1997. Division Manager, Environmental Assessment & Waste Management Division, Environmental Department, Houston Lighting & Power. Information Regarding the Potable Wells On-Site. 28 May 1997.
- 8. Bye, R.T. 1997. Division Manager, Environmental Assessment & Waste Management Division, Environmental Department, Houston Lighting & Power. Maps, Memoranda, And Photos Addressing The Inorganic Acid Collection Pond/Ash Pond, SWMU 9. 28 May 1997.
- 9. McGuire, W.F. 1984. Environmental Protection Department, Houston Lighting & Power. Letter to Ray Henry, Texas Department of Water Resources, Revised Part A Application. 9 October 1984.
- 10. McClelland Engineers, Inc. 1976. Geotechnical Investigation of the Ash Storage Area, W.A. Parish Generating Station for Houston Lighting & Power. 28 July 1976.
- 11. Texas Department of Water Resources (TDWR). 1983. TDWR Open Dump Inventory, Inspector's Comments for Houston Lighting & Power, W.A. Parish Generating Station, TDWR Registration No. 31631. 8 June 1983.

- 12. Resource Engineering. 1985. Hydrogeologic Evaluation at the W.A. Parish Generation Station for Houston Lighting & Power Co., Houston, Texas. December 1985.
- 13. Morse, III, Robert E. 1986. Attorney with Baker & Botts for Houston Lighting & Power Co. Answer to Findings of Violation and Administrative Order of 28 January 1986, Docket No. VI-86-020, EPA Region 6.
- 14. A.T. Kearney, Inc. 1988. Letter to Tom Clark, EPA, for Clean Closure Review for Houston Lighting & Power, SWMU 12. 9 December 1988.
- 15. Texas Water Commission. 1985. Letter to W.F. McGuire, Manager Environmental Protection Department, Houston Lighting & Power Co. for Approval of Drum Storage Area Closure Plan. 23 September 1985.
- 16. Norris, F. Warren. 1990. EPA. Inspection Report Review Potential Hazardous Waste Site. 2 August 1990.
- 17. Weber, Linda. 1990. EPA. Superfund Site Strategy Recommendation for HL&P Parish Station. 2 August 1990.
- 18. McGuire, W. F. 1984. Environmental Protection Department, Houston Lighting & Power. Affidavit of Exclusion from Hazardous Waste Permitting Requirement. 7 May 1984.
- 19. Bye, R.T. 1997. Division Manager, Environmental Assessment & Waste Management Division, Environmental Department, Houston Lighting & Power. Table Containing Wastewater Discharge Data From Various Permitted Outfalls That Are Associated With The Designated SWMUs.
- 20. Houston Lighting & Power. 1985. Office Memorandum Outlining the Class III Construction Debris Landfill, SWMU 14. 12 April 1985.
- Texas Natural Resource Conservation Commission (TNRCC). 1996. Notice of Registration Industrial and Hazardous Waste for Houston Lighting & Power, W.A. Parish EGS. 2 July 1996.
- 22. Carpenter, Bob. 1997. Houston Lighting & Power. Fax Communication to Joy Page, WESTON, with NPDES Permit and Outfalls. 17 July 1997.
- 23. Southern Petroleum Laboratories, Inc. 1996. Lab Data Analysis. 26 October 1996.
- 24. Carpenter, Bob. 1997. Houston Lighting & Power. Fax Communication. 24 July 1997.

- 25. Ishigo, Joy. 1997. WESTON. Personal Communication with Lucien Klejbuck, Supervising Engineer, Environmental Department, Houston Lighting & Power. 17 July 1997.
- 26. Houston Lighting & Power. 1995. Application for an Amendment to TNRCC Permit No. 5794 for the Injection of Boiler Cleaning Wastewater into Steam Generating Units 5 and 6 at the Houston Lighting & Power Co. W.A. Parish Electric Generating Station. November 1995.
- 27. TNRCC. 1994. Permit No. 6430A Fly Ash-Bottom Ash Disposal System for Houston Lighting & Power. 16 August 1994.
- 28. EPA. 1996. Drinking Water Regulations and Health Advisories. Office of Water, Washington, DC. EPA/822/R-96/001.
- 29. Bye, R.T. 1997. Division Manager, Environmental Assessment & Waste Management Division, Environmental Department, Houston Lighting & Power. Pontiometric Surface Map. 28 May 1997.
- 30. Cox, Carol. 1990. FIT Environmental Scientist, EPA Region 6. Personal Communication with Eddie Garcia, Soil Conservation Technician, U.S. Soil Conservation Service about Farming, Soil Types and Use of Smithers Lake. 2 March 1990.
- 31. Cox, Carol. 1990. FIT Environmental Scientist, EPA Region 6. Personal Communication with Eddie Garcia, Soil Conservation Technician, U.S. Soil Conservation Service about Use of Water from Rabbs Bayou; Erosion Control for Smithers Lake. 2 March 1990.
- 32. AIC (Agency Information Consultants). 1997. Waterwell Survey.
- 33. Federal Emergency Management Agency Flood Insurance Rate Map. 1986. Fort Bend County and Certain Political Districts. Map Panel Numbers 245, 400, 425, and 265. 5 August 1986.
- 34. Texas Parks and Wildlife Department Endangered Resource Branch. 1997. Fax Communication. 10 July 1997.
- 35. U.S. Department of Agriculture Soil Conservation Service. 1972. Hydric Soils in Fort Bend County. 14 January 1972.

APPENDIX A HEALTH AND SAFETY PLAN

		SITE HEAL	TH AND SAFETY PLAN	(HXT)	
Prepared by:			W.O. Nur	nber: 11098-112-027-0001-03	Date:5/20/
Department/Offi Site Name: HLY Client: US EPA	002- Houston ce: 1169 PP Parish Stat -START Address: 2753			ory: (describe briefly) an active electricity generating	station.
Scope of Wor	rk: (describe brief	ly)	<u> </u>		
•	econnaissance	_			
Site visit onl	y; site HASP not (necessary. List personnel h	ere and sign off below:	·	<u>.</u>
Regulatory St	atus:				
Site regulatory s CERCLA/SARA	,	Other Federal Agency		(Required to be On Site) t and Regulatory Status, determine the Standard H th Standard HASP will be used and append the app	
State	☐ State	USACE	form along with the Standard Pla Stack Test	m.	
NPL Site	NRC	☐ Air Force	Air Emissions	 	
OSHA	☐ 10 CFR 20		Asbestos Asbestos		
Hazard Com	munication (Req'd	See Attachment "D")	Industrial Hygiene		
1910	□ ₁₉₂₆	☐ State		<u> </u>	
Review and A	Approval Docum	nentation:	·	· · · · · · · · · · · · · · · · · · ·	
Reviewed by: DSO/RSO/CHS Other	Name (Print)	LAY	,0e 2	Signature Date:	5/21/97
Approved by: Project Director/ Project Manager	Dan M.	aclomore Ka	A Maximore)	5-21-97
Hazard Asses	sment and Equ	ipment Selection			
SHCS and/or the	e Site Manager ha he hazards knowr	ve evaluated conditions and n or expected to exist. (Refe	l verified that the personal pr	.132 at the site prior to personnel beginn rotective equipment selection outlined wi section 2 Personal Protection Program for Date:	thin this HASP is
Project start date: 22 May 1997 End date: 22 November 1997 Date: 22 November 1999			r:	Amendment date(s): By: 1. 2. 3. 4.	

WESTON REPRESENTATI	IVES					
Organization/Branch	Name/Title	Address	Telephone			
Weston	Dan MacLemore Project Manager	5599 San Felipe, Suite? Houston, TX 77056	700 (713)621-1620			
Weston	Carol Labreche Project Team leader	5599 Sun Felipe, Suite 700 Houston, TX 79056	(713)621-1620			
Weston	Joy Page Field Team Leader	5599 San Felipe, Suite M Houston, TX 77056	TOO (713)821-1620			
Roles and Responsibilities:						
WESTON SUBCONTRACT	rors					
Organization/Branch	Name/Title	Address	Telephone			
Roles and Responsibilities:						
SITE SPECIFIC HEALTH A						
		be conducted at this site is: Joy	V			
The SHSC has total responsibility for ensuring that the provisions of this Site HASP are adequate and implemented in the field.						
Changing field conditions may require decisions to be made concerning adequate protection programs. Therefore, the personnel assigned as SHSCs are experienced and meet the additional training requirements specified by OSHA in 29 CFR 1910.120						
Qualifications: At a minimized includes: OSHA 40-hr. First-aid, CPR, blood-box	mum, the SHSC will be a hazardous waste training one pathogen, dangerous good	a WESTON-certified Les of current refresher training ds, shipping, and WESTON	vel 0 SHSC. Training g as appliculle, currendt SHSC training.			
Designated alternates include: Eric Tate						

Hazard Assessment Gentlete Apartial why? Chily TCLP results (analytical)	HEALTH-AND SAFETY EVALUA						
Activities Covered Under This Plan: No. Tesk/Bubtesk Description Schedule 1. Site Reconnaissance Site walk-through with note-taking May 1997 and photographs. Types of Hazards: Number refer to one of the following hazed availuation forms. Complete heared availuation forms for each appropriate heared class. Physiochemical Chemically Toxic Rediction Biological Etiological Agent Infrarral exposure Control Infrarral exposure Cherr (Plent. insect, animal)		Hazard Assessment					
No. Tesk/Subtest Description Schedule Site Reconneissance	Background R						
Site Reconnaissance Site walk - through with note-taking May 1997 and photographs	Activities C	overed	Under This Plan:				
Types of Hazards: Numbers sefer to one of the following hazard evaluation forms. Complete hazard evaluation forms for each appropriate hazard class. Physiochemical Chemically Toxic Radiation Biological	No.		Task/Subtask				
Numbers refer to one of the following hazard evaluation forms. Complete hazard evaluation forms for each appropriate hazard class. Physiochemical Chemically Toxic Radiation Radiation Biological Biological Chemically Toxic Inhalation Carcinogen Ionizing: Etiological Agent Other (Plant, insect, animal) Explosive Contact Terstogen External exposure Other (Plant, insect, animal) Physical Hazards Other (Plant, insect, animal) Other (Pla	l.	Site	Reconnaissance	Site walk and photo	-through with note-to graphs.	cleing May 1997	
Numbers refer to one of the following hazard evaluation forms. Complete hazard evaluation forms for each appropriate hazard class. Physiochemical Chemically Toxic Radiation Radiation Biological Biological Chemically Toxic Inhalation Carcinogen Ionizing: Etiological Agent Other (Plant, insect, animal) Explosive Contact Terstogen External exposure Other (Plant, insect, animal) Physical Hazards Other (Plant, insect, animal) Other (Pla	·						
Inhalation	i'		the following hazard evel	uation forms. Complete hazare	d evaluation forms for each appropr	isto hazord class.	
Explosive	Physiochemics	el 🗊	Chemically Toxic		Radiation 3	Biological 2	
External exposure	Flammable	•				<u> </u>	
Corrosive	☐ Explosive			_	_	Other (Plant, insect, animal)	
Construction Activities Construction Act	Corrosive		,		☐ External exposure		
O ₂ Rich O ₂ Deficient OSHA Specific Hazard Substance Standard (Refer to HASP Form O4HASP.894 for Listing.) Source/Location of Contaminants and Hazardous Substances Directly Related to Tasks Indirectly Related to Tasks - Nearby Process(es) That Could Affect Team Members: Client Facility Other Surface Groundwater Soil Surface Water Sanitary Wastewater Client Briefing Arranged Construction Activities	Reactive		OSHA 1910.10	00 Substance	Non-ionizing:	Physical Hazards 4	
Osha Specific Hazard Substance Standard (Refer to HASP Form 04HASP.894 for Listing.) Source/Location of Contaminants and Hazardous Substances Directly Related to Tasks Indirectly Related to Tasks - Nearby Process(es) That Could Affect Team Members: Client Facility Other Surface Groundwater Soil Surface Water Sanitary Wastewater Client Briefing Arranged Client Briefing Arranged	O ₂ Rich		(Air Contaminan	ts)	□ _{UV} □ _{IR}	Construction Activities	
Source/Location of Contaminants and Hazardous Substances Directly Related to Tasks Indirectly Related to Tasks - Nearby Process(es) That Could Affect Team Members: Client Facility Other Surface Groundwater Soil Surface Water Sanitary Wastewater Client Briefing Arranged	O ₂ Deficien	nt	OSHA Specific	Hazard Substance	□ RF □ MicroW		
Directly Related to Tasks Indirectly Related to Tasks - Nearby Process(es) That Could Affect Team Members: Client Facility Other Surface Representation of the Could Affect Team Members: Client Facility Describe: Flectricity generating station of the Could Affect Team Members: Client Facility Describe: Flectricity generating station of the Could Affect Team Members: Client Facility Describe: Flectricity generating station of the Could Affect Team Members: Client Facility Describe: Flectricity generating station of the Could Affect Team Members:				04HASP.894 for Lieting.)	Laser		
Client Facility Other Surface Groundwater Soil Surface Water Sanitary Wastewater Process Wastewater Client Facility Describe: Flectricity generating station and a surface water Client Briefing Arranged			Source/Locat	tion of Contaminants	and Hazardous Substa	nces	
Other Surface Groundwater Describe: Electricity generating station process Wastewater Client Briefing Arranged Client Briefing Arranged	Directly Relate	d to Tasi	(8	Indirectly Related to To	asks - Nearby Process(es) Th	nat Could Affect Team Members:	
Groundwater Soil Surface Water Sanitary Wastewater Process Wastewater Describe: Electricity generating station and a statio	Air		Client Facility				
Soil Surface Water Sanitary Wastewater Process Wastewater	Other Surfa	ace		Nearby Non-client Facility			
Sanitary Wastewater Client Briefing Arranged Process Wastewater	· /	ter		Describe: Electrici	ty generating station	All the second s	
			vater Client Briefing Arranged				

	HEALTH AND SAFETY EVALUATION - TCHEMICAL HAZARDS					
NIA				N/A		
Chemical Contaminants of Concern				Identify hazardous materials used or on-site and		•
Provide the data requested for chemical contaminants on HASP Form 33HASP.894 or attach data sheets from an acceptable sources such as NIOSH pocket guide, condensed chemical dictionary, ACGIH TLV booklet, etc. List chemical and concentration below and locate data sheets in Appendix A of this HASP.			for all reagent type chemicals, solutions, or oth performing tasks related to this project could po- subcontractors and other parties working nearbook chemicals and the location of MSDS's. Obtain the hazardous materials they use or have on-sit chemicals and quantities below and locate MSI	roduce hazardous s by are informed of t from subcontracto te and identify loca	ubstances. Ensure that all the presence of these rs and other parties lists of tion of MSDS's here. List	
Chemical Na	me	Concentration (if I	known)	Chemical Name		Quantity
Antimony						
Antimony Barium Chromium Nickel Toluene Xylenes		•				·
Chromium						
Niekel						
77						
10 lineve						
Aylenes						
•	•					
	0	SHA SITE SPECI	FIC HA	AZARDOUS SUBSTANCES		
The following substances may require 1926 for additional information.	specific medical, training,	or monitoring based t	upon coi	ncentration or evaluation of risk. See the approp	riate citation listed	under 29 CFR 1910 or
☐ 1910.1001 Asbestos	☐ 1910.1002 Coal tar pit	tch volatiles	1 91	10.1003 4-Nitrobiphenyl	1910.1004 8	alpha Naphthylamine
1910.1005 [Reserved]	1910.1006 Methyl chle	oromethyl ether	1 91	10.1007 3,3'-Dichlorobenzidine (and its salts).	□ 1910.1008 t	ois-Chloromethyl ether
1910.1009 beta-Naphthylamine	ne 🛘 1910.1010 Benzidine 🔻 19		IO.1011 4-Aminodiphenyl	1910.1012 Ethyleneimine		
1910.1013 beta-Propiolactone 1910.1014 2-Acetylaminofluorene		1 91	10.1015 4-Dimethylaminoazobenzene	1910.1016 P	N-Nitrosodimethylamine	
☐ 1910.1017 Vinyl chloride	0.1017 Vinyl chloride		1 91	IO.1025 Lead	1 910.1027 (Cadmium
1910.1028 Benzene	☐ 1910.1029 Coke oven	emissions	1 91	10.1043 Cotton dust	1 910.1044 1	l,2-dibromo-3-chloropropane
1910.1045 Acrylonitrile	1910.1047 Ethylene oxide		10.1048 Formeldehyde	□ 1910.1050 f	Methylenedianiline	

HEALTH AND SAFETY EVALUATION - 2 BIOLOGICAL HAZARDS OF CONCERN				
Poisonous Plants (FLD	43)	Insects (FLD 43)		
Location/Task No(s).: Source: Route of Exposure:	☐ Known ☑ Suspect ☐ Inhalation ☐ Ingestion	Location/Task No(s).: Source: Route of Exposure:	☐ Known ☐ Suspect ☐ Inhalation ☐ Ingestion	
Team Member(s) Allergic:	Contact Direct Penetration Yes No	Team Member(s) Allergic:	Contact Direct Penetration Yes No	
Snakes, Reptiles (FLD		Animals (FLD 43)		
Location/Task No(s).: Source: Route of Exposure:	☐ Known ☐ Suspect ☐ Inhalation ☐ Ingestion ☐ Contact ☐ Direct Penetration	Location/Task No(s).: Source: Route of Exposure:	☐ Known Suspect ☐ Inhalation ☐ Ingestion ☐ Contact ☐ Direct Penetration	
Team Member(s) Allergic:	☐ Yes ☑ No	Team Member(s) Allergic:	☐ Yes No	
FLD 43 - WESTON Bioha	zard Field Operating Procedures: Att.	OP		
☐ Sewage	•	Etiologic Agents (List)		
Location/Task No(s).:		Location/Task No(s).:	☐ Known ☐ Suspect	
Source: Route of Exposure:	☐ Known ☐ Suspect☐ Inhalation ☐ Ingestion	Source: Route of Exposure:	☐ Inhalation ☐ Ingestion	
House of Exposure.	Contact Direct Penetration	House of Exposure.	Contact Direct Penetration	
Team Member(s) Allergic:	☐ Yes ☐ No	Team Member(s) Allergic:	☐ Yes ☐ No	
Immunization required:	☐ Yes ☐ No	Immunization required:	☐ Yes ☐ No	
Tetanus Vaccination within Past 7 yrs: Yes No (see Note #1 below)				
FLD 44 WESTON Bloodborne Pathogens Exposure Control Plan - First Aid Procedures: Att. OP				
FLD 45 - WESTON Bloodborne Pathogens Exposure Control Plan - Working with Infectious Waste: Att. OP				
Note #1: A tetanus injection is recommended every 10 years for employees with "normal exposure risks." However, if employees have frequent potential for exposure at "higher risk," as working with raw sewage, then a frequency of 7 years is recommended				

	HEALTH AND SAFETY EVALUATION — 3 RADIATION HAZARDS OF CONCERN NA							
				NONIONIZING RA	ADIATION			
Task #	Type of Nonionizing Radiation	Source Onsite	TLV/PEL	Wavelength Range	Control Measures	Monitoring Instrument		
	Ultraviolet							
	Infrared		•	,				
	Radio Frequency		•					
	Microwave							·
	Laser							
				IONIZING RAD	NATION		· · · · · · · · · · · · · · · · · · ·	
					DAC (µCi/mL)			······································
Task #	Radionuclide	Major Radiations	Radioactive Half-Life (Years)	D	w	Y	Surface Contamination Limit	Monitoring instrument
							'	
						·		
			•					
	i			,				

HE	ALTH AND FETY EVALUATION - 4 PHYS	ICAL HA	NDS OF CONCERN
Phy.Haz.Cond.	Physical Hazard	Att.OP	Weston OP Titles
Loud noise	Hearing loss/disruption of communication		FLD01 - Noise Protection
Inclement weather	Rain/humidity/cold/ice/snow/lightning		FLD02 - Inclement Weather
Steam heat stress	Burns/displaced oxygen/wet working surfaces		FLD03 - Hot Process - Steam
Heat/Stress	Burns/hot surfaces/low pressure steam		FLD04 - Hot Process - LT3
Ambient heat stress	Heat rash/cramps/exhaustion/heat stroke		FLD05 - Heat Stress Prevention/Monitoring
Cold Stress	Hypothermia/frostbite		FLD06 - Cold Stress
Cold/wet	Trench/paddy/immersion foot/edema		FLD07 - Wet Feet
Confined spaces	Falls/burns/drowning/engulfment/electrocution		FLD08 - Confined Space Entry
Explosive vapors	Thermal burns/impaction/dismemberment		FLD09 - Hot Work
Improper lifting	Back strain/abdomen/arm/leg muscle/joint injury		FLD10 - Manual Lifting/Handling Heavy Objec
Uneven Surfaces	Vehicle accidents/slips/trips/falls	/	FLD11 - Rough Terrain
Poor housekeeping	Slips/trips/falls/punctures/cuts/fires		FLD12 - Housekeeping
Structural integrity	Crushing/overhead hazards/compromised floors		FLD13 - Structural Integrity
Hostile persons	Bodily injury		FLD14 - Site Security
Remote Area	Slips/trips/falls/back strain/communication	/	FLD15 - Remote Area
Improper Cyl.Handling	Mechanical injury/fire/explosion/suffocation		FLD16 - Pressure Systems - Compressed Gas
Water Hazards	Poor visibility/entanglement/drowning/cold stress		FLD17 - Diving
Water Hazards	Drowning/heat/cold stress/hypothermia/falls		FLD18 - Operation and Use of Boats
Water Hazards	Drowning/frostbite/hypothermia/falls/electrocution		FLD19 - Working Over Water
Vehicle Hazards	Struck by vehicle/collision	-	FLD20 - Traffic
Explosions	Explosion/fire/thermal burns		FLD21 - Explosives
Moving mechanical parts	Crushing/pinch points/overhead hazards		FLD22 - Heavy Equipment Operation
Moving mech.parts	Overhead hazard/electrocution		FLD23 - Cranes/Lifting Equipment Operation
Working at elevation	Overhead hazards/falls/electrocution		FLD24 - Aerial Lifts/Manlifts
Working at elevation	Overhead hazard/falls/electrocution		FLD25 - Working at Elevation
Working at elevation	Overhead hazard/falls/electrocution/slips	·	FLD26 - Ladders
Working at elevation	Slips/trips/falls/overhead hazards		FLD27 - Scaffolding
Trench Cave-in	Crushing/falling/overhead hazards/suffocation		FLD28 - Excavating/Trenching
Improper material handling	Back injury/crushing-from load shifts		FLD29 - Materials Handling
Physiochemical	Explosions/fires from oxidizing, flam./corr.material		FLD30 - Hazardous Materials Use/Storage
Physiochemical	Fire and explosion		FLD31 - Fire Prevention/Response Plan Requi
Physiochemical	Fire		FLD32 - Fire Extinguishers Required
Structural integrity	Overhead/electrocution/slips/trips/falls/fire		FLD33 - Demolition
Electrical	Electrocution/shock/thermal burns		FLD34 - Utilities
Electrical	Electrocution/shock/thermal burns		FLD35 - Electrical Safety
Burns/Fires	Heat Stress/Fires/Burns		FLD36 - Welding/Cutting/Burning
Impact/thermal	Thermal burn/high pressure impaction/heat stress		FLD37 - High Pressure Washers
Impaction/electrical	Smashing body parts/pinching/cuts/electrocution		FLD38 - Hand and Power Tools
Poor visibility	Slips/trips/falls		FLD39 - Illumination
Fire/Explosion	Burns/impaction		FLD40 - Storage Tank
Communications	Disruption of Communications		FLD41 - Std. Hand/Emergency Signals
Energy/Release	Unexpected release of energy	-	FLD42 - Lockout/Tagout
	 -		

TASK-BY-TASK RISK ASSESSMENT (Complete One Sheet for Each Task)
TASK DESCRIPTION
Task 1: Site Reconnaissance consisting of a site walk-through with note-taking and photographs.
EQUIPMENT REQUIRED/USED (Be specific, e.g., hand tools, heavy equipment, instruments, PPE)
steel-toed boots, coveralls, OVA, mini RAM
POTENTIAL HAZARDS/RISKS
CHEMICAL
What Justifies Risk Level? The site is regularly analytically monitored wiresults sent to TNRCC. All areas to be visited have non-hazardous wastes.
PHYSICAL
What Justifies Risk Level? Trips, slips, Sulls, uneven ground
BIOLOGICAL
What Justifies Risk Level? Fire ants, snakes, spiders
RADIOLOGICAL
What Justifies Risk Level? No known or suspected sources
LEVELS OF PROTECTION/JUSTIFICATION
Level Oprotection while on-site.
SAFETY PROCEDURES REQUIRED AND/OR FIELD OPS UTILIZED
Follow standard operating procedures as a specified in the Weston SHSC manual.

TASK-BY-TASK RISK ASSESSMENT (Complete One Sheet for Each Task)
TASK DESCRIPTION
JACK DEGGINI 1.0.
EQUIPMENT REQUIRED/USED (Be specific, e.g., hand tools, heavy equipment, instruments, PPE)
POTENTIAL HAZARDS/RISKS
CHEMICAL
Hazard Present Rick Level: H DM DL
What Justifies Risk Level?
PHYSICAL
Hazard Present Risk Level: H M D L
What Justifies Risk Level?
BIOLOGICAL
Hezard Present Rick Lovel: H DM DL
□ Hazard Present Risk Lovel: □ H □ M □ L What Justifies Risk Lovel?
AAUST Sportings Light Frankl.
RADIOLOGICAL
Hazard Present Rick Level: H M M L
What Justifies Risk Level?
LEVELS OF PROTECTION/JUSTIFICATION
SAFETY PROCEDURES REQUIRED AND/OR FIELD OPS UTILIZED

PERSONNEL PRO	PERSONNEL PROTECTION PLAN				
Engineering Controls Describe Engineering Controls used as part of Personnel Protection Plan:					
Task(s) All					
Administrative Controls Describe Administrative controls used as part of Personnel Protection Plan:	·				
Task(s) All Outly Health & Safety meetings will be held to discus	ss pertinent HPS issues related to the site.				
Personnal Protective Equipment Action Levels for Changing Levels of Protection. Define Action Levels for up or do	own grade for each task:				
OVA: Bosed on historical TCLP data, choose toluene as most toxic action level: 2 x R90 = 100ppm 1.1 = 55 units mini-RAM: based on historical TCLP result choose antimony, barium, thronium. Each PEL/TLV = 0.5 mg/m ³ Action level: 0.25 mg/m ³					
Description of Leve					
Level D Task(s):	Level D Modified Task(s):				
☐ Head	☐ Head				
Eye and Face	Eye and Face				
☐ Hearing	☐ Hearing				
Arms and Legs Only	Arms and Legs Only				
Appropriate Work Uniform Coveralls	Whole Body				
Hand - Gloves	☐ _{Apron}				
Foot - Safety Boots Steel toed	☐ Hand - Gloves				
Fall Protection	Gloves				
Flotation	Gloves				
Other	Foot - Safety Boots				
	Boots				
	Boots				

Description of Levels of Protection						
Level C NA	Level B NA					
Task(s):	Task(s):					
☐ Head	☐ Head					
Eye and Face	Eye and Face					
☐ Hearing	☐ Hearing					
☐ Arms and Legs Only	☐ Arms and Legs Only					
☐ Whole Body	☐ Whole Body					
☐ Apron	☐ Apron					
☐ Hand - Gloves	☐ Hand - Gloves					
☐ Gloves	☐ Gloves					
☐ Gloves	Gloves					
Foot - Boots	□ Foot - Boots					
Boots	Boots					
□ Boots	□ Boots					
☐ Half Face	□ SAR - Airline					
☐ Cart./Canister	□ SCBA					
☐ Full Face	☐ Comb. Airline/SCBA					
☐ Cart./Canister	☐ Cascade System					
□ PAPR	Compressor					
☐ Cart./Canister	☐ Fall Protection					
□ туре С	☐ Flotation					
☐ Fall Protection	Other					
☐ Flotation						
Other						

O siti	SITE OR PROJECT HAZARD MONITORING ROGRAM							
	Direct Rea	ading Air Mo	nitoring Inst	ruments				
Instrument Selection and Initial Check					——————————————————————————————————————			
Reporting Format: A Field Notebook	☐ Field Date	a Sheets 🔲 /	Air Monitoring	Checked	p Report U Other	T		
instrument	Task No.(s)	Number Required	Number Received	Upon Receipt	Comment	Initial		
□ cgi								
□ o,		<u> </u>			·	1		
□ cgi/o₂								
CGI/O2/tox-PPM, H2S,H2S/CO	!	!			,			
□ RAD-GM	!							
□ Nel								
□ _{ZnS}	1							
Other	}	!						
□ _{PID}	1	}						
☐ HNU 10.2								
☐ HNU 11.7								
☐ Photovac, TMA		}						
□ о∨м		!						
DOWN DIE	AL.	1						
FID		!						
EOX 128	All	1	Ì					
Heath, AID, Other	1							
RAM, Mini-RAM, Other	AII							
□ _{Monotox}								
□ _{H₂} s								
□ cocL								
□ so,								
□ HCN	1	,						
☐ Other	1							
☐ Bio-Aerosol Monitor	1	·						
Detector Tubes	!	,						
Pump - MSA, Dräeger, Sensidyne								
☐ Tubes/type:		!				}		
☐ Tubes/type:								
Other		!						

SITE OR PROJECT HAZARD MONITORING PROGRAM Direct Reading Air Monitoring Instruments Calibration Record instrument, Calib. Mfg., **Final Setting** Model, Calib. Method Initial Setting Calibrator and Reading and Reading Initials Mfg.'s Other Date Time Material Equip. ID No.

SITE AIR MONITORING PROGRAM					
Direct Reading Air Monitoring Instruments					
Air Monitoring Instrument: OVA					
Air Monitoring Frequency: Periodically:					
Periodically:					
Continuously:					
Other:					
Monitoring Locations					
Upwind/downwind of site activities					
Near residents, etc.					
Key site activity locations:					
Decon area					
Staging area					
Excavation area					
Field lab area					
Storage tanks					
Lagoons					
Drums					
Fixed stations					
Pother: Breathing zone					
Air Monitoring Instrument: Mini-RAM					
Air Monitoring Frequency: Periodically:					
Periodically:					
Continuously:					
Other:					
Monitoring Locations					
Upwind/downwind of site activities					
Near residents, etc.					
Key site activity locations:					
Decon area					
区 Staging area					
Excavation area					
☐ Field lab area					
`□ Storage tanks					
Lagoons					
Drums					
Fixed stations					
10 Other: Breathing zone					

SITE AIR MONITORING PROGRAM

Action Levels

These Action Levels, if not defined by regulation, are some percent (usually 50%) of the applicable PEL/REL/TLV. That number must also be adjusted to

	Tasks	Action	Action	
Explosive atmosphere		Ambient Air Concentration	Confined Space Concentration	
	-	<10% LEL	O to 1% LEL	Work may continue. Consider toxicity potential.
		10 to 25% LEL	1 to 10% LEL	Work may continue. Increase monitoring frequency.
	,	>25% LEL	>10% LEL	Work must stop. Ventilate area before returning.
Oxygen		Ambient Air Concentration	Confined Space Concentration	
		<19.5% O ₂	<19.5% O ₂	Leave Area. Re-enter only with self-contained breathing apparatus.
		19.5% to 25% O2	19.5% to 23.5% O ₂	Work may continue. Investigate changes from 21%.
		>25% O ₂	>23.5% O ₂	Work must stop. Ventilate area before returning.
Radiation	_	< 3 times	background	Continue Work
	_	3 Times Background to < 1 mR/hour		Radiation above background levels (normally 0.01-0.02 mR/hr)g signifies possible source(s) radiation present. Continue investigation with caution. Perform thorough monitoring. Consult with a Health Physicist.
			Potential radiation hazard. Evacuate site. Continue investigation only upon the advice of Health Physicist.	
Organic gases and vapors	All	OVA> 55 units		stop work if sustained
Inorganic gases, vapors and particulates	A 11	0.25 mg/m?		stop work if sustained

SITE AIR MONITORING PROGRAM
Ambient Air Sampling
Check-situations which will require or action levels which will apply to deciding to institute or increase scope of planned air sampling.
No air sampling is required on this site.
Li An air sampling plan is incorporated in this HASP.
Meteorological Conditions Dry weather for days
Ambient temperature above*F
Wind increasing potential of more contaminant dispersion in or migration out of controlled area.
Activities which will require instituting or increasing scope of air sampling: Major spills
New site activity resulting in potential presence of new chemical hazards.
☐ Site activity increases airborne contaminants possibilities.
☐ Air sampling documentation required for:
Downgrading from stipulated level of protection Documenting no migration of contaminants offsite through air
Applicable Action Levels for instituting Air Sampling:
☐ Visible vapor/gas clouds or vapor levels, or
☐ Visible dust or particulate levels measured with Direct Reading Instrument, two-three times background or above action level sustained over 10-15 minute period.
The following requirements apply to air sampling:
Sampling Matrix/Air Interface - Monitor matrix/air interface and breathing zone periodically with DRI. If vapor levels > 2-3 times background, monitor continuously. Follow No. 4.
Container Opening - Monitor opening and breathing zone periodically with DRI. If vapor levels > 2-3 times background, monitor opening and breathing zone continuously. Follow No. 4.
Excavation/Drilling/Intrusive Work - Monitor at ground level and breathing zone periodically with DRI. If vapor levels > 2-3 times background, monitor opening and breathing zone continuously. Follow No. 4.
Breathing Zone - Ensure level of protection specified in HASP is being used. Consult HASP or Corporate Health and Safety relative to instituting personnel, area, or perimeter sampling.
Other ·

	SITE AIR MONITORING PROGRAM	APAD .
	Sample Location	
	Locations	Substances Sampled For
☐ Ambient background		
Personal samples, onsite		
Personal samples, offsite		
		· ·
Fixed, onsite samples		
Fixed, offsite samples		
Mobile offsite samples		
	·	
Mobile onsite samples		
Background sample stations		

	SITE AIR MONITORING PROGRAM							
	Air Sampling NA							
Personal Samplin	g Pumps - Gilian, S				No.			
			- Sorbent Tubes					
Task(s)	Location	Duration	Frequency	Туре	Analysis Method			
				<u> </u>	<u> </u>			
								
				 				
			 		 			
				 	 			
				 				
		Camalina M	ladia - Filter	<u></u>				
		Celliphing h	1 8 550	Ţ				
	·····							
-				<u> </u>				
				<u> </u>				
		· · · · · · · · · · · · · · · · · · ·		<u> </u>				
				ļ	 			
		_		<u> </u>	<u> </u>			
	· · · · · · · · · · · · · · · · · · ·	Sampling Me	dia - Impinger	1 .				
				· ·	<u> </u>			
				 				
				 				
			<u> </u>					
				† · · · · · · · ·				
				1	1			
		Sampling Me	edia - Air Bag					
<u> </u>								
				 				
				ļ	<u> </u>			
		·		 	 			
				-	-			
				<u> </u>	<u></u>			

		SITE AIR MO	ONITORING F	ROGRAM		
			Air Sampling	NA		
Hi-Volume Pumps	s - Gilian, SKC, M					
			pling Media - Fil	ter		
Task(s)	Location	Duration		equency	Туре	Analysis Method
	ļ					
		<u> </u>				
	 					
						<u> </u>
Portable Gas Chro Portable GC Analytic		Task(s):			Туре:	
Passive Dosimete	rs					
		Task(s)	Туре	Location	Frequency	Duration
Organic Vapor						
Mercury Vapor						
Paper Color Chan	ige					
Film Badge						٠
Liquid Media						
Wipe Sampling						
Wipe Sampling Plan:						
Atha camband Lieu.			•			
•						
		•				
ī						
	•					

SITE AIR MONITORING PROGRAM								
Physical Hazard and Miscellaneous Monitors and Detectors								
	Task(s) Calibration Location Frequency Required?/Method							
Sound Level Meter]						
Noise Dosimeter(s)								
Octave Band Analyzer								
Electric Circ. Detector]						
☐ Thermometer								
☐ Wind Speed Indicator	Ç							
☐ Barometer								
☐ Psychrometer								
☐ Infrared Thermometer								
Microwave Detector								
D pH Meter								
		Indicator Kits						
		Task(s)	Location	Frequency				
D pH Paper								
Peroxide Paper								
Chlor-N-Oil Kit								
☐ Hazerd Categorizing Kit				-				
Asbestos Test Kit								

			SITE AIR M	IONITORING	PROGRAM	<u> </u>			
			Work Locat	ion Instrume	ent Readings		 .	· · · · · · · · · · · · · · · · · · ·	
Location:				GM: Shield Probe/ Aerosol Thin Window					
% LEL	% 0 ,	PID (unite)	FID (units)	Monitor (mg/m³) mR/hr		cpm	Nel (uR/hr)	ZnS (cpm)	
	Monito	x (ppm)		Detector Tube(s)					
Sound Le	vels (dBA)	Illumination	рН	Other	Other	Other	Other	Other	
Location:			· · · · ·			eld Probe/			
				·			Vindow	Nel	ZnS
% LEL	% 0,	PID (units)	FID (units)	(mg/m ³)	mR/hr	cpm	(uR/hr)	(cpm)	
					:	<u> </u>	l <u> </u>	<u> </u>	
Monitox (ppm)				0	etector Tube(e)			
	<u> </u>	1							
Sound Le	vels (dBA)	Mumination	pН	Other	Other	Other	Other	Other	

		CONTINGENCIES			
	E	mergency Contacts and Phone Numbe	ors		
Agency		Contact		Phone Number	
Local Medical Emergency Facilit	ty (LMF)				
WESTON Medical Emergency C	ontact	EMR - Dr. Elayne Theriault	<u> </u>	1-800-229-3674	
WESTON Health and Safety		Corporate Health and Safety		(505)884-5050	
WESTON Health and Safety		SGR Health and Safety - Darryl Drenon		N507-1892 17131621-163	
Fire Department		<u> </u>	911	(610)-701-7406 - 3cot	
Police Department	911	112 0212			
Onsite Coordinator		Delbie Raca		343-2313	
Site Telephone		Debbie Ruca	178117	343-2313	
Nearest Telephone		Land Medical Emergency English(e)	L		
P. Ilya C.	ion Memo	Local Medical Emergency Facility(s)			
	ckson St.			Phone No.: (281)342-2811	
				Phone No.: (281) 372-2611	
	Mendo24				
Type of Service: Physical trauma only Go west on Jones RJ to FA762. Go north on FA762, Sminutes 15 minutes 15 m					
Physical trauma and			Y UNE	Ambulance Service:	
Available 24 hours	hospitul	is on the corner		911	
	s	econdary or Specialty Service Provide	er		
Name of Hospital:					
Address:				Phone No.:	
Name of Contact:				Phone No.;	
Type of Service:	Route to H	lospital (written detail):	.	Travel time from site:	
Physical trauma only Chemical exposure only	ļ			Distance to hospital:	
☐ Physical trauma and				Name/No. of 24-hr	
Chemical exposure Available 24 hours				Ambulance Service:	
Figure 1. Route to Hospital (Draw map to hospital here if space permits or attach on separate sheet.) See next page					
	7				
		•			




Figure 1 - Route to Hospital (Map)

		CONTINGENCIES				
		Response Plans				
Medical - General Provide First Aid as trained assess and determine need further medical assistance, Transport or arrange for transport after appropriate decontamination	l for	First Aid Kit:	Type 20 man 88P	Location Weston rehicle	Special First Ai Procedures: Cvanides on sit Yes No. If yes, contact LMF. Do they have antidote kit? Yes No	
·		Evewash required Yes No	Type Eye Stafe	Location - Weg	HF on site No. If yes, need neutralizing ointment for Fir Aid kit. Contac LMF.	
·		Shower required Yes A No	Туре	Location.		
Plan for Response to Spill/Release		Plan for Response to Fire/Explosion			Fire Extinguishers	
In the event of a spill or release, ensure safety, assess situation and perform containment and control measures as appropriate:	a. Clean up per MSDS if small or; Sound Alarm, call for assistance, Notify Emergency Coordinator b. Evacuate to predetermined safe place c. Account for personnel d. Determine if Team can respond safely e. Mobilize per Site Spill Response Plan	In the event of a fire or explosion, ensure personal safety, assess situation and perform containment and control measures as appropriate:	b. Evacuate to mined safe c. Account fo d. Use fire ex only if safe e. Standby to Emergency	Notify Coordinator o predeter- place or personnel tinguisher, and trained	Type/Location ABC/Weston vehicle	
Description of Spill Response Gear	Location .	Description (Other Fire Res	ponse Equipme	nt)	Location	
none						
Plan to Response to Security Problems call HLTP security and/or 911						
					·	

DECONTAMINATION PLAN	
Personnel Decontamination	
Consistent with the levels of protection required, step-by-step procedures for personnel decontaminal Protection are attached.	tion for each Level of
Levels of Protection Required for Decontamination Personnel	
The levels of protection required for personnel assisting with decontamination will be:	
Level B	Level D
Modifications include:	/(acro. 2
Disposition of Decontamination Wastes	
Provide a description of waste disposition including identification of storage area, hauler, and final dis	posal site, if applicable:
N A	
·	
	· ·
Equipment Decontamination	
A procedure for decontamination steps required for non-sampling equipment and heavy machinery foll Non-sampling equipment, such as monitoring equipment, will not be exposed contamination. They will be cleaned with a damp towel if necessary. The heavy machinery associated with the project other than a van and will not be driven it areas of known or suspected contamination	sed to sources of here will be no
Sampling Equipment Decontamination	·
Sampling equipment will be decontaminated in accordance with the following procedure:	
Only dedicated sampling equipment will be used and will be disposed	of in a
trush bag. (No sampling during Taske I activities)	

LEVEL D/MODIFIED LEVEL D DECONTAMINATION PLAN		
Check indicated functions or add steps as n	ecessary:	
Function	Description of Process, Solution, and Container	
Segregated equipment drop	Put equipment in hay	
Boot cover and glove wash		
Boot cover and glove rinse		
Tape removal - outer glove and boot		
Boot cover removal	Double bag for disposal	
Outer glove removal		
	HOTLINE	
☐ Suit/safety boot wash		
☐ Suit/boot/glove rinse		
Safety boot removal		
Suit removal	Bag coverally for laundry	
Inner glove wash		
Inner glove rinse		
Inner glove removal	Double lay for disposal	
Inner clothing removal		
	CRC/SAFE ZONE BOUNDARY	
Field wash	Wash hands before leaving site	
Redress	V -	
Disposal Plan, End of Day: All PPE will be sealed in	n bags. P disposed in an on-site dumpster	
Disposal Plan, End of Week:		
Same as daily plan.		
Disposal Plan, End of Project:		

LEVEL C DECONTAMINATION PLAN		
Check indicated functions or add steps as necessary:		
Function Description of Process, Solution, and Container		
Segregated equipment drop		
Boot cover and glove wash		
Boot cover and glove rinse		
Tape removal - outer glove and boot		
Boot cover removal		
Outer glove removal		
HOTLINE		
Suit/safety boot wash		
Suit/boot/glove rinse		
Safety boot removal		
Suit removal		
Inner glove wash		
Inner glove rinse		
Face piece removal		
Inner glove removal		
☐ Inner clothing removal		
CRC/SAFE ZONE BOUNDARY		
☐ Field wash		
□ Redress		
Disposal Plan, End of Day:		
·		
Disposal Plan, End of Week:		
<u> </u>		
Disposal Plan, End of Project:		
·		

LEVEL B C	DECONTAMINATION PLAN
Check indicated functions or add steps as necessary:	NA
Function	Description of Process, Solution, and Container
Segregated equipment drop	
Boot cover and glove wash	
Boot cover and glove rinse	
☐ Tape removal - outer glove and boot	
Boot cover removal	
Outer glove removal	
	HOTLINE
Suit/safety boot wash	
☐ Suit/SCBA/boot/glove rinse	
☐ Safety boot removal	
Remove SCBA backpack w/o disconnecting	
☐ Splash suit removal	
Inner glove wash	
Inner glove rinse	
SCBA disconnect and face piece removal	
Inner glove removal	
Inner clothing removal	
CRC/	SAFE ZONE BOUNDARY
Field wash	
Redress	
Disposal Plan, End of Day:	
Disposal Plan, End of Week:	
Disposal Plan, End of Project:	

SITE PERSONNEL AND CERTIFICATION STATUS						
WESTON						
Name: Joy Pag (Title: Enginee Task(s): /// Certification Level or Description: 0-5/8-T Medical Current Fit Test Current (Qual.) Fit Test Current (Quant.)	Name: Carol La Breche Title: Engineer Task(s): (A)) Certification Level or Description: D-5/6-T Medical Current Fit Test Current (Qual.) Training Current (Quantity)					
Name: Eric Tate Title: Engineer Task(s): All Certification Level or Description: 0-5/8-T	Name: Title: Task(s): Certification Level or Description:					
Name: Title: Task(s): Certification Level or Description: Medical Current Fit Test Current (Quant.) Training Current Fit Test Current (Quant.)	Name: Title: Task(s): Certification Level or Description: Medical Current Fit Test Current (Quant.) Training Current Fit Test Current (Quant.)					
Name: Title: Task(s): Certification Level or Description:	Name: Title: Task(s): Certification Level or Description:					
Name: Title: Task(s): Certification Level or Description: Medical Current Fit Test Current (Quant.) Training Current Fit Test Current (Quant.)	Name: Title: Task(s): Certification Level or Description: Medical Current (Quant.) Medical Current (Quant.) Fit Test Current (Quant.)					
Name: Title: Task(s): Certification Level or Description: Medical Current Fit Test Current (Qual.) Fit Test Current (Quant.)	Name: Title: Task(s): Cartification Level or Description: Medical Current Fit Test Current (Qual.) Fit Test Current (Quant.)					
TRAINING CURRENT - Training: All personnel, including visitors, entering the exclusion or contamination reduction zones must have certifications of completion o training in accordance with OSHA 29 CFR 1910, 29 CFR 1926 or 29 CFR 1910.120. FIT TEST CURRENT - Respirator Fit Testing: All persons, including visitors, entering any area requiring the use or potential use of any negative pressure respirator must have had as a minimum, a qualitative fit test, administered in accordance with OSHA 29 CFR 1910.134 or ANSI within the last 12 months. If site condition require the use of a full face negative pressure, sir purifying respirator for protection from Asbestos or Lead, employees must have had a quantitative fit test, administered according to OSHA 29 CFR 1910.1001 or 1025 within the last 6 months.						
MEDICAL CURRENT - Medical Monitoring Requirements: All personnel, including visitors, entering the exclusion or contamination reduction zones must be certific as medically fit to work, and to wear a respirator, if appropriate, in accordance with 29 CFR 1910, 29 CFR 1926/1910 or 29 CFR 1910.120. The Site Health and Safety Coordinator is responsible for verifying all certifications and fit tests.						
SITE PERSONNEL AND CER	ITIFICATION STATUS					
Subcontractor's Health and Sa	efety Program Evaluation					
Address: Activities to Be Conducted by Subcontractor:						
Evaluation C	riteria					

Medical program meets OSHA/WESTON criteria Acceptable Unacceptable Comments:	Personal protective equipment Acceptable Unacceptable Comments:	available	Onsite monitoring equipment available calibrated and operated property Acceptable Unacceptable Comments:		
Safe working procedures clearly specified Acceptable Unacceptable Comments:	Training meets OSHA/WESTO	N criteria	Emergency procedures Acceptable Unacceptable Comments:		
Decontamination procedures Acceptable Unacceptable Comments:	General health and safety prog Acceptable Unacceptable Comments:	ram evaluation	Additional comments: Subcontractor has agreed to and will conform with the WESTON HASP for this Project. Subcontractor will work under his own HASP which has been accepted by Corporate Health and Safety.		
Evaluation Conducted by:	Subcontra	ctor	Date:		
	Training Current Fit Test Current (Quant.)	Name: Title: Task(s):			
Name: Title: Task(s): Certification Level or Description:	Training Current Fit Test Current (Quant.)	Name: Title: Task(s):	el or Description:		
Name: Title: Task(s): Certification Level or Description:	Training Current Fit Teat Current (Quant.)	Name: Title: Task(s):	el or Description:		

HEALTH AND SAFETY PLAN APPROVAL/SIGNOFF FORM

Site Name: HL+P Parish Station

wo# 110998-112-027-0001-03

Address: 2759 Jones Road Thompsons, TX

I understand, agree to and will conform with the information set forth in this Health and Safety Plan (and attachments) and discussed in the Personnel Health and Safety briefing(s).

Name	Signature	Date
Eric Tate	me tato	5/22/37
Carol La Breche	Carol Pa Breche	5/22/97
Jay L. Page	I Dage	5/2/97
		•
<u> </u>		
		•

TRAINING AND BRI	EFING TOPICS
The following items will be covered at the site specific training meet	ting, daily or periodically.
Site characterization and analysis, Sec. 3.0, 29 CFR 1910.120 i	□ Level A
Physical hazards, Table 3.2	Level B
Chemical hazards, Table 3.1	Level C
Animal bites, stings, and poisonous plants	☑ Level D
Etiologic (infectious) agents	☐ Monitoring, Sec. 7.0; 29 CFR 1910.120 h
☐ Site control, Sec. 8.0; 29 CFR 1910.120 d	Decontamination, Sec. 9.0; 29 CFR 1910.120 k
Engineering controls and work practices, Sec. 8.5; 25 CFR 1910.120 g	Emergency response, Sec. 10.0; 29 CFR 1910.120 I
Heavy machinery	Elements of an emergency response, Sec. 100; 29 CFR 1910.120 i
□ Forklift	Procedures for handling site emergency incidents, Sec. 10.0; 29 CFR 1910.120 I
☐ Beckhoe	Offsite emergency response, 29 CFR 1910.120
☐ Equipment	☐ Handling drums and containers, 29 CFR 1910.120 j
☐ Tools	Opening drums and containers
☐ Ladder 29 CFR 1910.27 d	☐ Electrical material handling equipment
Overhead and underground utilities	Radioactive waste
☐ Scaffolds	☐ Shock sensitive waste
Structural integrity	Laboratory waste packs
Unguarded openings - wall, floor, ceilings	☐ Sampling drums and containers
Pressurized air cylinders	Shipping and transport, 49 CFR 172.101
Personnel protective equipment, Sec. 5.0; 25 CFR 1910.120 g; 29 CFR 1910.134	Tank and vault procedures
Respiratory protection, Sec. 5.8; 29 CFR 1910.120 g; Z88.2-1980	☐ Illumination, 29 CFR 1910.120 m
	☐ Sanitation, 29 CFR 1910.120 n
	·

ATTACHMENT "A" CHEMICAL CONTAMINANTS DATA SHEETS

(Use HASP Form 33HASP.894 or attach appropriate data sheets.)

	HEALTH AND SAFETY EVALUATION — CHEMICAL HAZARDS							
Hazardous Substance/Tasks	Physical Properties	Normal Physical State	State At Site/Proj. Temp.	Characteristics	Exposure Limits	Route(s) of Exposure/ Symptoms	Monitoring Instruments/ Ionization Potential + % Response	
CAS No: 108-88-3 Synonyms:	Explosive Flammable Corrosive Reactive Water Reactive Oxidizer Radioactive	Solid Liquid Gas Incompatible	Solid Liquid Gas With:	pH: FP: LEL: 1.1% UEL: 7.1% Auto. Ig.: BP: 232° F MP: Sp. Gr.: 0.87 Vap. D.: Vap. P.: 21 mm	□ CA □ PEL 200ppM □ TLV 100ppm □ IDLH Stoppm. □ Only toxicological data available □ Other:	Inhalation Ingestion Skin Absorption Contact Direct Penetration Other:	PID 11.7 eV 10.2 eV OVM CGI OVA IP:	
Methyl beneze Tolvol				H,O Sol.: Other:			% Response:	

	HEALTH AND SAFETY EVALUATION - CHEMICAL HAZARDS								
Hazardous Substance/Tasks	Physical Properties	Normal Physical State	State At Site/Proj. Temp.	Characteriatics	Exposure Limits	Route(s) of Exposure/ Symptoms	Monitoring Instruments/ Ionization Potential + % Response		
XYLENES:	Explosive Corrosive	Solid Liquid Gas	Solid Liquid Gas	pH: FP: LEL: /./ %	□ CA **D PEL 100 ppm. **ILV 100 ppm	Inhalation Ingestion Skin Absorption	□ PID □ 11.7 eV □ 10.2 eV		
7, 2011 = 3	Reactive Water Reactive Oxidizer	□ Gas	u cas	UEL: 7.0% Auto. Ig.: BP: 281° F	DOOD Only toxicological data available	Contact Direct Penetration Other:	OVM CGI		
CAS No:	☐ Radioactive	Incompatible		MP: Sp. Gr.:	Other:				
Synonyms:		Strong oxidizers Pacids		Pacids Vap. D.: Vap. P.: 9 m m H,0 Sol.: 0,02%		Symptoms:	IP:		
				Other:		·	% Response:		

	HEALTH AND SAFETY EVALUATION — CHEMICAL HAZARDS							
Hazardous Substance/Tasks	Physical Properties	Normal Physical State	State At Site/Proj. Temp.	Characteristics	Exposure Limits	Route(s) of Exposure/ Symptoms	Monitoring Instruments/ Ionization Potential + % Response	
NICKEL CAS No: 7440-02-0 Synonyms:	Explosive Flammable Corrosive Reactive Water Reactive Oxidizer Radioactive Other	Solid Liquid Gas	Salid Liquid Gas	pH: FP: LEL: UEL: Auto. lg.: BP: \$1390	I CA My/m³ My/m	Inhalation Ingestion Skin Absorption Contact Direct Penetration Other: Symptoms:	PID 11.7 eV 10.2 eV OVM CGI OVA MINITERAM IP: % Response:	

	HEALTH AND SAFETY EVALUATION - CHEMICAL HAZARDS							
Hazardous Substance/Tasks	Physical Properties	Normal Physical State	State At Site/Proj. Temp.	Characteristics	Exposure Limite	Route(s) of Exposure/ Symptoms	Monitoring Instruments/ Ionization Potential + % Response	
CHROMIUM	Explosive Flammable Corrosive Reactive Water Reactive Oxidizer	Solid Liquid Gas	Solid Liquid Gas	PH: FP: LEL: UEL: Auto. lg.: BP: 4788°	PEL 1 Mg/m3 PEL 1 Mg/m3 TLV 0.5 Mg/m3 DIDLH 250 Mg/m3 Only toxicological data available	Ingestion Ingestion Skin Absorption Contact Direct Penetration Other:	PID 11.7 eV 10.2 eV OVM CGI OVA	
CAS No: 7440-47-3 Synonyms: Chrome	Radioactive	Incompatible With: Strong oxidizest alkalis		MP: 3452° F sp. Gr.: 7.14 Vap. D.: Vap. P.: ØMM	Other:	Symptoms:	OVA المكام: RAM	
ORI OTHER		·		H ₂ O Sol.: Ø			% Response:	

	HEALTH AND SAFETY EVALUATION - CHEMICAL HAZARDS							
Hazardous Substance/Tasks	Physical Properties	Normal Physical State	State At Site/Proj. Temp.	Characteristics	Exposure Limits	Route(s) of Exposure/ Symptoms	Monitoring Instruments/ Ionization Potential + % Response	
ANTIMONY	Explosive Flammable Corrosive Reactive Water Reactive Oxidizer	State Solid Liquid Gas	Schid Liquid Gas	pH: FP: LEL: UEL: Auto. lg.: BP: 2975°F	□ CA ■ PEL O. 5 Mg/m³ ■ TLV O.5 Mg/m³ ■ IDLH Somg/m³ □ Only toxicological data available	Inhalation Ingestion Skin Absorption Contact Direct Penetration Other:	PID 11.7 eV 10.2 eV OVM CGI	
CAS No: 7440-36-0 Synonyms:	Radioactive Other	Incompatible Strong oxid	e With:	MP: 1166°F Sp. Gr.: 6.69 Vap. D.: Vap. P.: Øm M H ₂ O Sol.: Ø	Other:	Symptoms:	OVA Mini-RAM IP:	
				Other:		·	% Response:	

	HEALTH AND SAFETY EVALUATION — A CHEMICAL HAZARDS							
Hazerdous Substance/Tasks	Physical Properties Explosive	Normal Physical State	State At Site/Proj. Temp. Solid	Characteristics	Exposure Limits	Route(s) of Exposure/ Symptoms Inhelation	Monitoring Instruments/ Ionization Potential + % Response	
BARIUM	Flammable Corrosive Reactive Water Reactive Oxidizer	Liquid Gas	Liquid Gas	FP: LEL: UEL: Auto. lg.: BP: -	PEL O.5 Mg/m ³ MILV O.5 Mg/m ³ MIDLH 50 Mg/m ³ Only toxicological data available	Ingestion Skin Absorption Contact Direct Penetration Other:	11.7 eV 10.2 eV OVM CGI OVA	
CAS No: 10022-31-8 Synonyms: Barium nitrate	☐ Radioactive	Incompatible Acids 70		MP: /094°C Sp. Gr.: 3.24 Vap. D.: Vap. P.: H ₂ O Sol.:	Other:	Symptoms:	Minishim IP:	
				Other:		·	% Response:	

ATTACHMENT "B" MATERIAL SAFETY DATA SHEETS (MSDS)

ATTACHMENT "C" SAFETY PROCEDURES/FIELD OPS (FLDOP'S)

ATTACHMENT "D" SITE SPECIFIC HAZARD COMMUNICATION PROGRAM

In order to ensure an understanding of and compliance with the Hazard Communication Standard, WESTON will utilize this checklist/document (or similar document) in conjunction with the WESTON Written Hazard Communications Program as a means of meeting site or location specific requirements.

While responsibility for activities within this document reference the WESTON Safety Officer, it is the responsibility of all personnel to effect compliance. Responsibilities under various conditions can be found within the WESTON Written Hazard Communication Program.

To ensure that information about the dangers of all hazardous chemicals used by WESTON are known by all affected employees, the following hazardous information program has been established. All affected personnel will participate in the hazard communication program. This written program as well as WESTON's Corporate Hazard Communication Program will be available for review by any employee, employee representative, representative of OSHA, NIOSH or any affected employer/employee on a multi-employer site.

<u> </u>	Site or other location name/address:
	Site/Project/Location Manager:
	Site/Location Safety Officer:
	List of chemicals complied. format: HASP: Other:
	Location of MSDS Files:
_	Training Conducted by (name and date):
	Indicate format of training documentation: Field Log: Other:
_	Client briefing conducted regarding hazard communication:
	If multi-employer site, indicate name of affected companies:
_	
	Other employer(s) notified of chemicals, labelling and MSDS information:
	WESTON notified of other employer's or clients hazard communication program as necessary.

List of Hazardous Chemicals

A list of known hazardous chemicals used by WESTON personnel must be prepared and attached to this document or in a centrally identified location with the MSDS's. Further information on each chemical may be obtained by reviewing the appropriate MSDS's. The list will be arranged to enable cross reference with the MSDS file and the label on the container. The SO or location manager is responsible for ensuring the chemical listing remains up-to-date.

Container Labeling

The WESTON Safety Officer (SO) will verify that all containers received from the chemical manufacturer, importer or distributor for use on site will be clearly labeled.

The SO is responsible for assuring labels are placed where required and for comparing MSDS's and other information with label information to ensure correctness.

Material Safety Data Sheets (MSDS)

The SO is responsible for establishing and monitoring WESTON's MSDS program for the location. The SO will make sure procedures are developed to obtain the necessary MSDS's and will review incoming MSDS's for new or significant health and safety information. He/she will see that any new information is passed on to the affected employees. If an MSDS is not received at the time of initial shipment, the SO will call the manufacturer and have a MSDS delivered for that product in accordance with the requirements of WESTON's Written Hazard Communication Program.

A log for, and copies of, MSDS's for all hazardous chemicals in use will be kept in the MSDS folder at a location known to all site workers. MSDS's will be readily available to all employees during each work shift. If an MSDS is not available, immediately contact the WESTON SO or designated alternate. When revised MSDS's are received the SO will immediately replace the old MSDS's.

Employee Training and Information

The SO is responsible for the WESTON site-specific personnel training program. The SO will ensure that all program elements specified below are supplied to all affected employees.

At the time of initial assignment for employees to the work site or whenever a new hazard is introduced into the work area employees will attend

- a health and safety meeting or briefin, includes the information indicated below.
- Hazardous chemicals present at the worksite
- Physical and health risks of the hazardous chemicals
- The signs and symptoms of overexposure
- Procedures to follow if employees are overexposed to hazardous chemicals
- Location of the MSDS file and written hazard communication program
- How to determine the presence or release of hazardous chemicals in the employees work area
- · How to read labels and review MSDS's to obtain hazard information
- Steps WESTON has taken to reduce or prevent exposure to hazardous chemicals
- How to reduce or prevent exposure to hazardous chemicals through use of controls procedures, work practices and personal protective equipment
- Hazardous, non-routine tasks to be performed (if any)
- Chemicals within unlabled piping (if any)

Hazardous Non-Routine Tasks

When employees are required to perform hazardous non-routine tasks the affected employee(s) will be given information by the SO about the hazardous chemicals he or she may utilize during such activity. This information will include specific chemical hazards, protective and safety measures the employee can use and steps WESTON is using to reduce the hazards. These steps include, but are not limited to, ventilation, respirators, presence of another employee and emergency procedures.

Chemicals in Unlabeled Pipes

Work activities may be performed by employees in areas where chemicals are transferred through unlabeled pipes. Prior to starting work in these areas, the employee shall contact the SO at which time information as to; the chemical(s) in the pipes, potential hazards of the chemicals or the process involved, and safety precautions which should be taken will be determined and presented.

Multi-Employer Worksites

It is the responsibility of the SO to provide other employers with information about hazardous chemicals imported by WESTON to which their employees may be exposed, along with suggested safety precautions. It is also the responsibility of SO and the site manager to obtain information about hazardous chemicals used by other employers to which WESTON employees may be exposed. WESTON's chemical listing will be made available to other employers as requested. MSDS's will be available for viewing as necessary.

The location, format and/or procedures for accessing MSDS information must be relayed to affected employees.